

AD-A087 329

NEW JERSEY DEPT OF ENVIRONMENTAL PROTECTION TRENTON
NATIONAL DAM SAFETY PROGRAM. ELECTRIC LIGHT POND DAM (NJ00245).--ETC(U)
FEB 80 J TALERICO

F/6 13/13

DACW61-79-C-0011


NI

UNCLASSIFIED

1 of 2
0000000000000000



08/32



MICROCOPY RESOLUTION TEST CHART
Nikon NAC-BK5000 - C-1000 Series - A

55
ADA 087329

LEVEL II

HACKENSACK RIVER BASIN
PASCACK BROOK, BERGEN COUNTY
NEW JERSEY

ELECTRIC LIGHT
POND DAM
NJ 00245 S

DTIC
ELECTE

JUL 31 1980

PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

APR
DISTRIBUTION UNLIMITED.

E
APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED.



THIS DOCUMENT IS BEST QUALITY PRACTICALLY.
THE COPY IS DUE TO DDC CONTAINED A
SIGNIFICANT NUMBER OF PAGES WHICH DO NOT
REPRODUCE EASILY.

DEPARTMENT OF THE ARMY

Philadelphia District
Corps of Engineers
Philadelphia, Pennsylvania

DDC-17-1000-1
1000-1

FEBRUARY 1980

80 7 25 135

NOTICE

THIS DOCUMENT HAS BEEN REPRODUCED
FROM THE BEST COPY FURNISHED BY
THE SPONSORING AGENCY. ALTHOUGH
IT IS RECOGNIZED THAT CERTAIN POR-
TIONS ARE ILLEGIBLE, IT IS BEING
RELEASED IN THE INTEREST OF MAKING
AVAILABLE AS MUCH INFORMATION AS
POSSIBLE.

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE			READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NJ00245	2. GOVT ACCESSION NO. AD-A089329	3. RECIPIENT'S CATALOG NUMBER	
4. TITLE (and Subtitle) Phase I Inspection Report	5. TYPE OF REPORT & PERIOD COVERED 9 FINAL report		
National Dam Safety Program. Electric Light Pond Dam (NJ00245), [REDACTED] Bergen County, New Jersey.	6. PERFORMING ORG. REPORT NUMBER		
7. AUTHOR(s) Hackensack River Basin, Pascack Brook, Bergen County, New Jersey. Phase John Talarico	7. CONTRACT OR GRANT NUMBER(s) 15 DACW61-79-C-0011		
8. PERFORMING ORGANIZATION NAME AND ADDRESS Fredric R. Harris, Inc. 1 Inspection 453 Amboy Ave. Woodbridge, NJ 07095 Report.	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS 12 118		
11. CONTROLLING OFFICE NAME AND ADDRESS NJ Department of Environmental Protection Division of Water Resources P.O. Box CN029 Trenton, NJ 08625	12. REPORT DATE 11 Feb 80		
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) U.S. Army Engineer District, Philadelphia Custom House, 2d & Chestnut Streets Philadelphia, PA 19106	13. NUMBER OF PAGES 101		
10 John Talarico	15. SECURITY CLASS. (of this report) Unclassified		
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.			
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)			
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia 22151.			
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams National Dam Safety Program Dam Safety Electric Light Pond Dam, NJ Visual Inspection Structural analysis Spillways			
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report cites results of a technical investigation as to the dam's adequacy. The inspection and evaluation of the dam is as prescribed by the National Dam Inspection Act, Public Law 92-367. The technical investigation includes visual inspection, review of available design and construction records, and preliminary structural and hydraulic and hydrologic calculations, as applicable. An assessment of the dam's general condition is included in the report.			

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



IN REPLY REFER TO
NAPEN-N

DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
CUSTOM HOUSE—2D & CHESTNUT STREETS
PHILADELPHIA, PENNSYLVANIA 19106

Honorable Brendan T. Byrne
Governor of New Jersey
Trenton, New Jersey 08621

21 JUL 1990

Accession For	
NTIS	GRA&I
DDC TAB	<input checked="" type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Dist.	Avail and/or special
A	<i>[Signature]</i>

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Electric Light Pond Dam in Bergen County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Electric Light Pond Dam, a high hazard potential structure, is judged to be in fair overall condition. The dam's three spillways are considered inadequate because a flow equivalent to 91 percent of the Spillway Design Flood -SDF- would cause the dam to be overtopped. The SDF, in this instance, is one half of the Probable Maximum Flood (PMF). The decision to consider the spillways inadequate instead of seriously inadequate is based on the determination that overtopping of the dam would not significantly increase the hazard to loss of life downstream from that which would exist just before overtopping failure. To ensure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillways' adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within twelve months from the date of approval of this report. This should include the installation of a tailwater gage and a determination of the ability of the dam to withstand overtopping. Within three months of the consultant's findings, remedial measures to ensure spillway adequacy should be initiated.

b. The following remedial actions should be completed within twelve months from the date of approval of this report:

(1) Investigate the embankment for animal burrows and fill in the burrows with an impervious material.

APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED.

NAPEN-N

Honorable Brendan T. Byrne

(2) Repair all eroded, cracked and spalled concrete with epoxy cement.

(3) Clean and repaint all the steel-work on the operating mechanisms. Repair the stem stand concrete support and install a new valve at the west spillway.

(4) Install new discharge conduit at the west spillway.

(5) Install an access bridge across the east spillway and install a new sluice gate with the operating mechanism located on the access bridge.

(6) All brush and trees should be removed from the downstream slope and emergency spillway to avoid problems which may develop from their roots. The embankment should then be seeded to develop a growth of grass for surface erosion protection.

(7) The owner should inspect the dam for seepage during the refilling operation.

c. The owner should develop an emergency action plan (if one is not already available) outlining actions to be taken by the operator to minimize downstream effects of an emergency and establish a flood warning system for the downstream communities within three months from the date of approval of this report.

d. Within one year from the date of approval of this report the owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman Harold Hollenbeck of the Ninth District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

NAPEN-N

Honorable Brendan T. Byrne

An important aspect of the Dam Inspection Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,



1 Incl
As stated

JAMES G. TON
Colonel, Corps of Engineers
District Engineer

Copies furnished:
Mr. Dirk C. Hofman, P.E., Deputy Director
Division of Water Resources
N.J. Dept. of Environmental Protection
P.O. Box CN029
Trenton, NJ 08625

Mr. John O'Dowd, Acting Chief
Bureau of Flood Plain Regulation
Division of Water Resources
N.J. Dept. of Environmental Protection
P.O. Box CN029
Trenton, NJ 08625

ELECTRIC LIGHT POND DAM (NJ00245)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 12 November and 3 December 1979 by Harris-ECI Associates, Inc., under contract to the State of New Jersey. The State, under agreement with the U.S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Electric Light Pond Dam, a high hazard potential structure, is judged to be in fair overall condition. The dam's three spillways are considered inadequate because a flow equivalent to 91 percent of the Spillway Design Flood -SDF- would cause the dam to be overtopped. The SDF, in this instance, is one half of the Probable Maximum Flood (PMF). The decision to consider the spillways inadequate instead of seriously inadequate is based on the determination that overtopping of the dam would not significantly increase the hazard to loss of life downstream from that which would exist just before overtopping failure. To ensure adequacy of the structure, the following actions, as a minimum, are recommended:

a. The spillways' adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within twelve months from the date of approval of this report. This should include the installation of a tailwater gage and a determination of the ability of the dam to withstand overtopping. Within three months of the consultant's findings, remedial measures to ensure spillway adequacy should be initiated.

b. The following remedial actions should be completed within twelve months from the date of approval of this report:

(1) Investigate the embankment for animal burrows and fill in the burrows with an impervious material.

(2) Repair all eroded, cracked and spalled concrete with epoxy cement.

(3) Clean and repaint all the steel-work on the operating mechanisms. Repair the stem stand concrete support and install a new valve at the west spillway.

(4) Install new discharge conduit at the west spillway.

(5) Install an access bridge across the east spillway and install a new sluice gate with the operating mechanism located on the access bridge.

(6) All brush and trees should be removed from the downstream slope and emergency spillway to avoid problems which may develop from their roots. The embankment should then be seeded to develop a growth of grass for surface erosion protection.

(7) The owner should inspect the dam for seepage during the refilling operation.

c. The owner should develop an emergency action plan (if one is not already available) outlining actions to be taken by the operator to minimize downstream effects of an emergency and establish a flood warning system for the downstream communities within three months from the date of approval of this report.

d. Within one year from the date of approval of this report the owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam.

APPROVED:


JAMES G. TON

Colonel, Corps of Engineers
District Engineer

DATE: 7 July 1980

HACKENSACK RIVER BASIN
PASCACK BROOK, BERGEN COUNTY
NEW JERSEY

ELECTRIC LIGHT POND DAM

NJ00245

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED.

DEPARTMENT OF THE ARMY
PHILADELPHIA DISTRICT, CORPS OF ENGINEERS
PHILADELPHIA, PENNSYLVANIA 19106

JANUARY, 1980

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name: Electric Light Pond Dam, I.D. NJ 00245
State Located: New Jersey
County Located: Bergen
Stream: Pascack Brook
River Basin: Hackensack River
Date of Inspection: November 12 and December 3, 1979

Assessment of General Condition

Electric Light Pond Dam is an earthfill embankment dam containing a west spillway, an east spillway, and just right of the east spillway, an emergency spillway. The overall condition of the dam is considered fair. There is no major sign of distress or instability of the embankment although minor surface cracks were noted in the emergency spillway. The operating mechanism for the east spillway low level outlet is missing, and at the time of inspection, the west spillway outlet control was not operative. The hazard potential is rated as "high".

The adequacy of Electric Light Pond Dam is considered questionable in view of its lack of spillway capacity to pass the SDF (1/2 PMF) without overtopping the dam. The spillway is capable of passing a flood equal to 45 percent of the PMF (90 percent of the 1/2 PMF), and is rated "inadequate".

At present, the engineering data available is not sufficient to make a definitive statement on the stability of the dam. The following actions, therefore, are recommended along with a timetable for their completion. All recommended studies should be conducted by an engineer qualified in the design and construction of dams.

1. Carry out a more precise hydrologic and hydraulic analysis of the dam within twelve months, to determine the need and type of mitigating measures necessary. Based on the results of these studies, remedial measures should be instituted. This should include the installation of a tailwater gage.
2. Investigate embankment for animal burrows and fill in the burrows with an impervious material.

3. Repair all eroded, cracked and spalled concrete with epoxy cement, within twelve months.
4. Clean and repaint all the steel-work on the operating mechanisms. Repair stem stand concrete support and install a new valve at the west spillway. This work should be completed within twelve months.
5. Install new discharge conduit at west spillway, within twelve months.
6. Install access bridge across east spillway and install new sluice gate with operating mechanism located on access bridge, within twelve months.
7. All brush and trees should be removed from the downstream slope and emergency spillway to avoid problems which may develop from their roots. The embankment should then be seeded to develop a growth of grass for surface erosion protection. This program should be started within twelve months.
8. The owner should develop an emergency action plan (if one is not already available) outlining actions to be taken by the operator to minimize downstream effects of an emergency and establish a flood warning system for the downstream communities within three months.
9. The owner should inspect the dam for seepage during the refilling operation.

Furthermore, while of a less urgent nature, the following additional action is recommended and should be carried out within twenty-four months.

The owner should develop within one (1) year after formal approval of the report, written operating procedures and a periodic maintenance plan to insure the safety of the dam.



John P. Talerico, P.E.
HARRIS-ECI ASSOCIATES



Photo taken on February 8, 1980

E L E C T R I C L I G H T P O N D D A M

View from East spillway (portion of right abutment in foreground) toward Emergency spillway, embankment, West spillway and abandoned powerhouse to its right. Water in the reservoir, right, has been drained for dry dredging operations.

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the office of the Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

TABLE OF CONTENTS

ASSESSMENT OF GENERAL CONDITIONS

OVERVIEW PHOTO

PREFACE

	<u>Page</u>
SECTION 1 PROJECT INFORMATION	1
1.1 General	1
1.2 Description of Project	1
1.3 Pertinent Data	5
SECTION 2 ENGINEERING DATA.....	8
2.1 Design	8
2.2 Construction.....	8
2.3 Operation	8
2.4 Evaluation.....	8
SECTION 3 VISUAL INSPECTION.....	9
3.1 Findings	9
SECTION 4 OPERATION PROCEDURES.....	11
4.1 Procedures	11
4.2 Maintenance of Dam.....	11
4.3 Maintenance of Operating Facilities.....	11
4.4 Evaluation	11
SECTION 5 HYDRAULIC/HYDROLOGIC	12
5.1 Evaluation of Features.....	12
SECTION 6 STRUCTURAL STABILITY	14
6.1 Evaluation of Structural Stability.....	14
SECTION 7 ASSESSMENT/REMEDIAL MEASURES	16
7.1 Dam Assessment	16
7.2 Remedial Measures	17

TABLE OF CONTENTS CONTINUED

<u>PLATES</u>	<u>No.</u>
KEY MAP AND VICINITY MAP	1 & 1A
GEOLOGIC MAP.....	2
DRAWINGS OF DAM.....	3-10
 <u>APPENDICES</u>	
APPENDIX A - CHECK LIST - VISUAL OBSERVATIONS CHECK LIST - ENGINEERING, CONSTRUCTION, MAINTENANCE DATA	1- 14
APPENDIX B - PHOTOGRAPHS	
APPENDIX C - SUMMARY OF ENGINEERING DATA	1
APPENDIX D - HYDROLOGIC COMPUTATIONS.....	1 - 36

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

ELECTRIC LIGHT POND DAM, I.D. NJ00245

SECTION 1

1. PROJECT INFORMATION

1.1 General

a. Authority

The National Dam Inspection Act (Public Law 92-367, 1972) provides for the National Inventory and Inspection Program by the U.S. Army Corps of Engineers. This inspection was made in accordance with this authority under Contract C-FPM No. 35 with the State of New Jersey who, in turn, is contracted to the Philadelphia District of the Corps of Engineers, and was carried out by the engineering firm of Harris-ECI Associates, Woodbridge, New Jersey.

b. Purpose of Inspection

The visual inspection of Electric Light Pond Dam was made on November 12, 1979. The purpose of the inspection was to make a general assessment as to the structural integrity and operational adequacy of the dam embankment and its appurtenant structures.

c. Scope of Report

The report summarizes available pertinent data relating to the project; presents a summary of visual observations made during the field inspections; presents an evaluation of hydrologic and hydraulic conditions at the site; presents an evaluation as to the structural adequacy of the various project features; and assesses the general condition of the dam with respect to safety.

1.2 Description of Project

a. Description of Dam and Appurtenances

Electric Light Pond Dam is an earthfill dam approximately 588 feet long and 20.6 feet high with two main spillways and one emergency spillway. The main spillways are located at the east and west end of the dam with the emergency spillway located immediately west of the east spillway. The top of the embankment is 12 feet wide and the upstream and downstream faces are sloped at 2.5H: 1V and 2H: 1V, respectively. A 12-inch wide concrete core wall extends from the west spillway 94 feet into the embankment.

The main spillways are ungated modified concrete ogee overflows with crest elevations 5.6 feet below the top of the embankment. The east spillway is 20.0 feet wide while the west spillway is 47 feet wide and is reinforced by two concrete buttresses. The emergency concrete spillway which was constructed over the section of embankment that failed in 1945, is 66 feet wide with a crest elevation 2.5 feet above the main spillways. A steel sheeting cutoff wall is located under the emergency spillway and extends 21 feet into the embankment.

Two 48-inch concrete pipes located at the east and west spillways are used to lower the lake. They are controlled by sluice gates on the upstream face of the dam. The discharge through the east spillway is directly into the downstream channel while the discharge through the west spillway goes through an abandoned power house before entering the channel. The gate at the west spillway is a hand operated rising stem steel gate. There is no operating mechanism at the east spillway and the gate must be removed manually to open it.

Two boring programs were performed for this dam. In 1946, Riley Engineering and Drilling Co. drilled six holes along the dam's crest (Plate 9). An additional program was performed in 1951. A Hobelman, Argenti, and Kuhn construction plan (Plate 10), shows four toe borings. The driller was not identified.

The six crest borings classify the embankment as sand and gravel with the foundation, generally, clay, fine sand and gravel. Rock, identified as sandstone, is greater than 20 feet below the dam's toe.

A generalized description of soil conditions is contained in Report No. 4, Bergen and Hudson Counties, Engineering Soil Survey of New Jersey, by Rutgers University. The report describes the downstream area as recent alluvium. The remaining portions of the lake is classified as stratified drift.

Recent alluvium are soils transported to their present location by surface water and stream flow. The soils range in size from clayey silt to gravelly silt and sand. They have been altered from their parent material by alluvial action and sedimentation. Stratified drift is non-residual materials deposited by the Wisconsin glacier. The drift is assorted, relatively homogeneous material, mainly sand sizes, with varying amounts of silt and gravel. The underlying rock is deep and is described on Geologic Overlay Sheet 23 as the Brunswick Formation. This formation is primarily shale with interbedded sandstone.

b. Location

Electric Light Pond Dam is located on Pascack Brook in the Borough of Park Ridge, Bergen County, New Jersey. It is approximately 1,300 ft. upstream from the Park Avenue Bridge and is accessible from Mill Avenue.

c. Size Classification

According to the "Recommended Guidelines for Safety Inspection of Dams" by the U.S. Department of the Army, Office of the Chief of Engineers, the dam is classified in the dam size category as being "small", since its storage area of 65 acre-feet is less than 1,000 acre-feet. The dam is also classified as small because its height of 20.6 feet is less than 40 feet. The overall size classification of Electric Light Pond is small.

d. Hazard Classification

A hazard potential classification of "high" has been assigned to the dam on the basis that a hypothetical failure would result in excessive damage to commercial and borough owned property downstream of the dam. In addition, the immediate downstream area is used for recreational purposes with a park, pool, and tennis courts so that the possibility exists of the loss of more than a few lives in the event of dam failure.

e. Ownership

Electric Light Pond Dam is owned by:

Borough of Park Ridge
55 Park Avenue
Park Ridge, New Jersey 07656

Attention: Mr. Charles E. Gasior
Borough Administrator
(201) 573-1800

f. Purpose

Electric Light Pond Dam is presently used for recreational and esthetic purposes only. It was originally used to generate electricity.

g. Design and Construction History

Information concerning the original dam, which was constructed around 1900, is very limited. During the July, 1945 flood, the dam was overtopped and a section of embankment failed. The extent of the damages caused by the failure are not available. In 1952, modifications and reconstruction of the existing dam began with the intention of increasing the overflow capacity. To accomplish this the two existing spillways were lowered and an emergency spillway was provided at the area of embankment failure. Construction was completed in 1954, and since then there have not been any additional modifications.

h. Normal Operation Procedures

The discharge from the pond is normally unregulated and is allowed to naturally balance discharge with inflow into the pond. There are two low-level outlets in the pond, one at the east spillway and one at the west spillway. The outlets are controlled by sluice gates which when open discharge the water through 4 ft. concrete openings. The one at the east spillway discharges directly into the downstream channel while the one at the west spillway discharges through the abandoned powerhouse into the downstream channel. The gate through the west spillway is manually operated while the gate at the east spillway is presently inoperative.

1.3 Pertinent Data

a. Drainage Area 14.2 sq.mi.

b. Discharge at Dam Site

Maximum known flood at dam site: July 23, 1945.
 Height of overtop unknown.

Ungated spillway capacity at
elevation of top of dam: 4,634 cfs (elev. 137.6) NGVD

Total spillway capacity at
maximum pool elevation (SDF): 5,490 cfs (elev. 137.84) NGVD

c. Elevation (Feet above NGVD)

Top of dam: 137.6

Maximum pool design surcharge (SDF): 137.84

Recreation pool: 132.2

Spillway Crest - East and West: 132.0

Emergency spillway crest: 134.5

Streambed at centerline of dam: 117.0 (estimated)

Maximum tailwater - East:

- West: 120.5 (estimated)
 119.5 (estimated)

d. Reservoir

Length of maximum pool: 1,700 ft. (estimated)

Length of recreation pool: 1,400 ft. (estimated)

e. Storage (acre-feet)

Recreation pool: 22 (elevation 132.2 NGVD)

Top of dam: 63.0

Maximum pool (SDF): 65.0

f. Reservoir Surface (acres)

Top of dam: 9

Spillway crest: 7

g. Dam

Type:	Earth fill with three concrete spillways: 2 main (East & West) and one emergency spillway.
Length:	588 ft.
Height:	20.6 ft.
Top width:	12 ft.
Side slopes - Upstream: - Downstream:	2.5H:1V 2.0H:1V
Zoning:	Unknown
Impervious core:	Concrete = $94 \pm$ ft; Steel sheeting = $20 \pm$ ft; and remainder is unknown
Cutoff:	None
Grout curtain:	None

h. Diversion and Regulating Tunnel

N/A

i. Spillway

Type - East and West: Emergency:	Modified concrete ogee; ungated. Concrete; trapezoidal; ungated.
Length of weir - East: - West: - Emergency:	20 ft. 47 ft. 66 ft.
Crest elevations - East and West: Emergency:	132 ft. NGVD 134.5 ft. NGVD
Gates:	None
U.S. Channel:	Electric light pond
D/S Channel:	D/S channel from East spillway merges with D/S channel from West spillway at a distance of approx. 800 ft. from East spillway.

j. Regulating Outlets

Low level outlet: 2-48-inch pipes

Controls: Manually operated gate valve
(now, in open position)

Emergency gate: None

Outlet: 122.2 NGVD

SECTION 2

2. ENGINEERING DATA

2.1. Design

Computations pertaining to the original construction of the dam are not available from the New Jersey Department of Environmental Protection (NJ-DEP) or from the owner. Drawings dated 1940, are on file at the Trenton office of the NJ-DEP. Also on file at the NJ-DEP are plans for reconstruction of the dam in 1952.

Some soil data is available from borings taken through the existing embankment in 1946 and in 1951. The sampling was done as part of the modification and reconstruction of the dam. In addition, other borings were taken within the pond in 1975 for the dredging of the pond. No soil properties were given for any of the borings.

2.2 Construction

No records have been found covering the original construction of the dam. However, there is information available pertaining to the repairs and modifications of the dam during 1952-1954. This information, in the form of the contract drawings, specifications and progress reports, is on microfiche at the NJ-DEP. A brief summary of the reconstruction history has been provided in Section 1.2g.

2.3 Operations

- No records of operation of the dam are available. The pond is allowed to operate naturally without regulation.

2.4 Evaluation

a. Availability

The engineering data concerning the reconstruction of the dam and the boring data of the existing embankment is available from the NJ-DEP.

b. Adequacy

The engineering data available was adequate to perform hydrologic and hydraulic computations, but was insufficient to perform stability computations. A preliminary assessment could be made based on visual observations.

c. Validity

Information contained in the drawings and checked by limited field measurements appears to be valid.

S E C T I O N 3

3. VISUAL INSPECTION

3.1 Findings

a. General

The visual inspection of Electric Light Pond Dam revealed the dam and spillways to be in fair condition and in need of repairs.

At the time of the visual inspection water in the reservoir was drained to permit dry dredging operations currently being performed. The reservoir water was being channeled into low-level outlet drains at the abandoned powerhouse near the west spillway and at the east spillway. According to the owner, the reservoir should be refilled during the summer of 1980.

b. Dam

The earth embankment appears to be sound. No surface cracking on the embankment or at the toe was noted. Erosion of the embankment was limited to a worn footpath behind the left abutment of the west spillway. No misalignment of the embankment in the horizontal or vertical plane was observed. Numerous trees, small and medium sized, are growing on top and on both sides of the embankment. No cracks or spalling of the concrete core, or parting of the steel sheeting on top of the embankment, were noticed. No seepage or sloughing was found in any portion of the downstream face of the embankment. No evidence of burrowing by animals was observed; however, at the time of the inspection the embankment was covered with leaves, therefore the possibility does exist that there may be burrow holes in the embankment.

c. Appurtenant Structures

1. Spillways

Three concrete spillways exist-one on the embankment's west side, one on its east side (emergency spillway) and one adjacent to the emergency spillway. No seepage or leakage was noticed at any of the spillways. Severe spalling was noticed at the left interface and at the two buttresses of the west spillway. Minor spalling was noticed at the right interface of the west spillway. A vertical crack was noticed in the retaining wall on the right side of the west spillway. Severe spalling and a horizontal crack were noticed on the right abutment of the east spillway. Surface cracks along the emergency spillway were noticed with trees and shrubs growing in these cracks. A longitudinal crack exists across the east spillway. Horizontal and vertical alignment of the crests of the spillways appeared good.

2. Outlet Works

There was no cracking or spalling of the concrete surfaces in the stilling basins. A four foot diameter concrete sluice way with trash rack , located at the east base of the abandoned powerhouse and west of the west spillway, is in good condition. The sluice gate for this west spillway was open for the above mentioned current dredging operations. Water through the powerhouse exits through two concrete notches (3ft. x 2 ft. & 5 ft. x 3 ft.) at the south base of the powerhouse into the channel. A four foot diameter concrete sluice way, at the west base of the east spillway, is in good condition. No sliding gate and no operating mechanism were present at the sluice way. Water through the sluice way at the east spillway exits onto a concrete apron.

The concrete foundation supporting the operating mechanism is substantially deteriorated and additional bracing (steel channels) have been added to support the stand. Also, at the time of inspection the representatives from the borough were unable to lift the hand wheel over the valve stem to demonstrate the gate operation.

d. Reservoir Area

The reservoirs' side slopes are moderate. There is no indication of slope instability. As previously mentioned, water in the reservoir was drained to permit dry dredging operations for the removal of silt buildup.

e. Downstream Channel

Two downstream channels exist--one from the west spillway and one from the east. These channels meet approximately 800 feet from the east spillway. Channels are in good condition.

Approximately 700 feet from the east spillway, 100 feet before both channels meet, a roadway bridge crosses the east channel.

SECTION 4

4. OPERATIONAL PROCEDURES

4.1 Procedures

There are no formal operating procedures established at Electric Light Pond Dam. It is used to impound water for recreational activities with the level of the lake normally being maintained by unregulated discharge over the spillways. Prior to major storms the level in the pond is lowered by opening the sluice gate in the west spillway to allow for the additional runoff.

4.2 Maintenance of the Dam

The dam is maintained by the Borough of Park Ridge. There is no program of regular inspection and maintenance of the dam and appurtenant structures.

4.3 Maintenance of Operating Facilities

The low-level outlet operating facilities consist of two sluice gates. The operating mechanism for the east gate is missing and the gate is removed manually when they need to open it. The opening and closing of the gates is the responsibility of the Electric and Water Division of the Borough.

4.4 Evaluation

The dam and pond appear to be maintained in a serviceable condition; although the concrete has been allowed to deteriorate without repair. Such repairs as recommended should be undertaken to prevent further deterioration.

SECTION 5

5. HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

a. Design

The drainage area above Electric Light Pond Dam is approximately 14.2 square miles. A drainage map of the watershed of the dam site is presented on Plate 1, Appendix D.

The topography within the basin is moderately sloped. Elevations range from approximately 640 feet above NGVD at the north end of the watershed to about 132 feet at the dam site. Land use patterns within the watershed are 50% woodland and 50% residential development scattered around the basin.

The evaluation of the hydraulic and hydrologic features of the dam and lake was based on criteria set forth in the Corps Guidelines and additional guidance provided by the Philadelphia District, Corps of Engineers. The Spillway Design Flood for the dam falls in a range of $\frac{1}{2}$ PMF to PMF. In this case, the lower end of the range, $\frac{1}{2}$ PMF, is chosen since the dam height is at the middle to lower range of the size category.

The probable maximum flood (PMF) was calculated from the probable maximum precipitation using Hydrometeorological Report No. 33 with standard reduction factors.

The unit hydrograph was determined by Snyder's Method. Snyder's peaking coefficient C_p was specified by the COE as 0.83. The synthetic unit hydrograph was developed with the aid of the HEC1-DB program.

Initial and infiltration loss rates were applied to the Probable Maximum Precipitation to obtain rainfall excesses. The rainfall excesses were applied to the unit hydrograph to obtain the PMF and various ratios of PMF utilizing program HEC1-DB.

The SDF peak outflow calculated for the dam is 5490 cfs. This value is derived from the $\frac{1}{2}$ PMF, and results in overtopping of the dam, assuming that the lake was originally at the spillway crest elevation.

The stage-outflow relation for the spillway was determined from the geometry of the spillway and dam utilizing HEC1-DB program.

The reservoir stage-storage capacity relationship was computed directly by the conic method, utilizing the HEC1-DB program. The conic method assumes that the reservoir capacity resembles a series of vertically stacked cones. The reservoir surface areas at various elevations were measured by planimeter from a U.S.G.S. Quadrangle topographic map. Reservoir storage capacity included surcharge levels exceeding the top of the dam, and the spillway rating curve was based on the assumption that the dam remains intact during routing.

A breach analysis indicates that the hazard potential for loss of life downstream, due to dam failure from overtopping, is not significantly greater than that which exists without failure.

Drawdown calculations indicate that to empty the lake to an elevation of approximately 122.2' NGVD through the two low-level sluices would take 0.9 hours, assuming a 2 cfs/square mile inflow.

b. Experience Data

No record of reservoir stage or spillway discharge are maintained for this site.

c. Visual Observation

Two downstream channels exist-one from the west spillway and one from the east-joining approximately 800 feet downstream from the east spillway. Channels are well defined with trees growing on their banks. A roadway bridge crosses the east channel approximately 700 feet from the east spillway. A municipal building, Borough of Park Ridge, a lumber yard and a recreation area are approximately 1200 feet from the east spillway.

The reservoir's side slopes are moderate and do not exhibit signs of instability. At the time of the inspection the water in the reservoir was drained to permit dry dredging operations for the removal of silt buildup.

d. Overtopping Potential

A storm of magnitude equivalent to the SDF would cause overtopping of the dam to a height of 0.27 feet. Computations indicate that the dam can pass approximately 45% of the PMF without overtopping the dam crest. Since one half the PMF is the Spillway Design Flood (SDF) for this dam, according to the Recommended Guidelines for Safety Inspection of Dams by the Corps of Engineers, the spillway capacity of the dam is assessed as "inadequate".

SECTION 6

6. STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations

The dam structure shows no sign of cracking, settlement or differential movement that would suggest instability. Since the pond was drained for the dredging operation it could not be determined whether or not there is seepage. Trees and brush on the top and both sides of the embankment as well as along the top of the emergency spillway could pose a threat to stability and should be removed.

b. Design and Construction Data

No design computations were uncovered during the report preparation phase. No data was obtained on the type and limits of core between the steel sheet piling and the concrete core sections. No embankment or foundation soil parameters are available for carrying out a conventional stability analysis on the embankment. No construction data or specifications relating to the degree of embankment compaction are available for use in the stability analysis.

c. Operating Records

No operating records are available relating to the stability of the dam. During the July 1945 flood, the dam was overtopped washing out a portion of the embankment near the east spillway.

d. Post-Construction Changes

A history of the dam is given in Section 1.2g. The principal changes relating to the stability of the dam are: the widening of the embankment, the lowering of the two main spillways and the construction of an emergency spillway in 1952.

e. Static Stability

A static stability analysis was not performed for Electric Light Pond Dam because the lack of data on which to base assumptions of material properties within embankment zones might produce misleading results, but based on the findings of the visual inspection, the preliminary assessment of static stability is that it is satisfactory.

f. Seismic Stability

The dam is located in Seismic Zone 1, as defined in Recommended Guidelines for Safety Inspection of Dams, prepared by the Corps of Engineers. In general, projects located in Seismic Zones 0,1 and 2 may be assumed to present no hazard from earthquake, provided the static stability conditions are satisfactory and conventional safety margins exist. Since static stability safety factors have not been confirmed, it cannot be stated that seismic stability is satisfactory.

S E C T I O N 7

7. ASSESSMENT/REMEDIAL MEASURES

7.1 Dam Assessment

a. Safety

The dam has been inspected visually and a review has been made of the available engineering data. This assessment is subject to the limitations inherent in the visual inspection procedures stipulated by the Corps of Engineers for a Phase 1 report.

The safety of Electric Light Pond dam is in question because the dam does not have adequate spillway capacity to pass the PMF or even $\frac{1}{2}$ of the PMF without overtopping. The dam's present spillway capacity is about 45% of the PMF.

Embankment overtopping will carry with it a high risk of total embankment failure by the erosive action of the overflowing water.

No definitive statement pertaining to structural safety can be made without knowledge of the phreatic surface across the embankment section , the engineering properties of the various embankment and foundation materials and their distribution or zoning throughout the dam's section.

b. Adequacy of Information

The information uncovered was adequate to perform hydrologic and hydraulic computations. The data was insufficient to perform an adequate evaluation of dam stability.

c. Urgency of Studies

Carry out a more precise hydrologic and hydraulic analysis within twelve months, to determine the need and type of mitigating measures necessary. This should include the installation of a tailwatergage, and determination of the ability of the dam to withstand overtopping.

7.2 Remedial Measures

a. Alternatives for increasing Spillway Capacity

Alternatives for increasing spillway capacity are as follows:

1. Increase the embankment height thus permitting a higher discharge to pass over the spillway and reducing the possibility of overtopping.
2. Lower the emergency spillway crest elevation.
3. Widen the emergency spillway structure.
4. A combination of any of the above alternatives

b. Recommendations to be undertaken within 12 months

1. Investigate embankment for animal burrows and fill in the burrows with an impervious material.
2. Repair all eroded, cracked and spalled concrete with epoxy cement.
3. Clean and repaint all the steel-work on the operating mechanisms. Repair stem stand concrete support and install a new valve at the west spillway.
4. Install new discharge conduit at west spillway.
5. Install access bridge across east spillway and install new sluice gate with operating mechanism located on access bridge.
6. All brush and trees should be removed from the downstream slope and emergency spillway to avoid problems which may develop from their roots. The embankment should then be seeded to develop a growth of grass for surface erosion protection.

The following additional actions are recommended:

1. The owner should develop an emergency action plan (if one is not already available) outlining actions to be taken by the operator to minimize downstream effects of an emergency and establish a flood warning system for the downstream communities within three months.

2. The owner should inspect the dam for seepage during the refilling operation.


d. O & M Procedures

The owner should develop, within one (1) year after formal approval of the report, written operating procedures and a periodic maintenance plan to insure the safety of the dam.


PLATES

ELECTRIC LIGHT POND DAM
BORO OF PARK RIDGE
BERGEN COUNTY, N. J.

N




Scale in Miles (Approx.)



KEY MAP

PLATE I




Scale in Feet (Approx.)

2,000 0 2,000 4,000 6,000 8,000 10,000

VICINITY MAP

PLATE 1A



LEGEND

TRIASSIC

Rb Brunswick Formation
Soft Red Shale with Interbeds of Red Sandstone

NOTE: Glacial - Fluvial Sands and Gravels Mantling
Bedrock in Pascack Brook Valley not Shown

GEOLOGIC MAP
ELECTRIC LIGHT POND DAM





8

GENERAL INFORMATION

BY GENEVA C. COOPER


1940

1940

1940

PEATE 3

1



GENERAL PROFILE
FOR THE REPAIR AND RECONSTRUCTION OF DAM
ELECTRIC LIGHT POND
BOROUGH OF PARK RIDGE
ILLINOIS

PLATE 4

**THE SIGHT CONTOURS
PROPOSED FOR DETERMINING CONTOUR**






PLATE 5






ELEVATION AND SECTIONS
EAST SPILLWAY AND EMERGENCY SPILLWAY
ELECTRIC LIGHT POND
BOROUGH OF PARK RIDGE
ILLINOIS

NOEL
WORK


ENTIRE DRAWING
ESTIMATED

SECTION E


PLATE 6



PLAN
scale 1:50



1344000
100000




WEST SPILLWAY
ELECTRIC LIGHT POND
BORDERS OF PARK RIDGE
KODAK SAFETY FILM

FILE

PLATE 7

1



J



MIDDLE SECTION


WEST SIDE

1945-2-24


PLATE 8

1





NOTE. 250 lb hammer
2 or Drop



**PROPOSED PARK RIDGE DAM
TEST BORING DATA
BOROUGH OF PARK RIDGE, N J
HARLEY & GARLICK, ENGINEERS
FAIRLAWN, N J.**

RILEY ENGINEERING & DRILLING CO.
1733 EAST 31ST ST., BROOKLYN 10

DATE - DEC 5, 1946


Thomas J. Reilly
GENERAL MANAGER

ENCL 160

DD-5 Proposed

1

E Mill Road



CD 1 proposed for the port

CD 1 proposed for the port
for the port

CD 1 proposed for the port
for the port
for the port
for the port

2
SPILLING
PROBLEMS
PROBLEMS
DECODED
BY 1321.JC.12.05.93
BY 1321.JC.12.05.93

PLATE 10

APPENDIX A
CHECK LIST - VISUAL OBSERVATIONS
CHECK LIST - ENGINEERING, CONSTRUCTION
MAINTENANCE DATA

CHECK LIST
VISUAL INSPECTION
PHASE 1

Name Dam ELECTRIC LIGHT POND
(AKA MILL POND DAM &
SILVER LAKE) County Bergen State New Jersey Coordinators NJ-DEP

Date(s) Inspection November 12, 1979 Weather Cloudy Temperature 50°F
December 3, 1979

Pool Elevation at Time of Inspection * NGVD
* Water in reservoir was drained for current dredging operations.

Inspection Personnel:

November 12, 1979: December 3, 1979:

Chuck Chin
Henry King
Thomas Lakovich
Eugene Koo
James McCormick

Owner/Representative:

November 12 and December 3, 1979

Charles E. Gasior, Borough Administrator
Borough of Park Ridge
Park Ridge, NJ 05656

Tailwater at Time of Inspection 116.5 NGVD

<u>VISUAL EXAMINATION OF</u>	<u>CONCRETE SPILLWAYS</u>	<u>OBSERVATIONS</u>	<u>REMARKS AND RECOMMENDATIONS</u>
SEEPAGE OR LEAKAGE None noticed.	Water in reservoir drained for current dry dredging operations.		Inspect for seepage during the refilling operation.
		STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS Severe spalling at left interface and at two buttresses at the west spillway. Minor spalling was noticed at the right interface of the west spillway. Severe spalling and a horizontal crack were noted on the right abutment of the east spillway.	Repair spalling and crack.
		DRAINS Yes-low level outlet drains-see "OUTLET WORKS".	
		WATER PASSAGES Yes-low level outlet-see "OUTLET DRAINS".	
			FOUNDATIONS Unknown

CONCRETE SPILLWAYS		REMARKS AND RECOMMENDATIONS
VISUAL EXAMINATION OF	OBSERVATIONS	
SURFACE CRACKS CONCRETE SURFACES	Concrete slabs show cracks along emergency spillway, numerous trees growing in these cracks. A longitudinal crack exists across the east spillway.	Remove trees and repair cracks.
STRUCTURAL CRACKING	None visible	
VERTICAL & HORIZONTAL ALIGNMENT	Good	
MONOLITH JOINTS	Good	
CONSTRUCTION JOINTS	Vegetation growing in construction joints at emergency spillway.	Remove vegetation.

VISUAL EXAMINATION OF	EMBANKMENT	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
SURFACE CRACKS			
None Noticed.			
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE			
No visible movement or cracking at or beyond toe was observed.			
SLoughing OR Erosion OF EMBANKMENT AND ABUTMENT SLOPES			
No sloughing or erosion was visible.			
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST			
Good.			
RIPRAP FAILURES			
N/A			

VISUAL EXAMINATION OF	EMBANKMENT	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
<u>Numerous Trees</u> , small and medium sized, growing on top of and on both sides of earth embankment and on the emergency spillway. <u>Concrete Core</u> , one foot wide, visible on top of embankment for a distance of 94 feet from west spillway. <u>Steel Sheeting</u> visible for distance of 21 feet from the emergency spillway.			Remove trees.
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM Minor erosion behind left abutment of west spillway			
ANY NOTICEABLE SEEPAGE None noticed.		Water in reservoir drained for current dry dredging operations.	
STAFF GAGE AND RECORDER None			
DRAINS None			

VISUAL EXAMINATION OF	OUTLET WORKS	REMARKS AND RECOMMENDATIONS
	OBSERVATIONS	
CRAKING & SPALLING OF CONCRETE SURFACES IN STILLING BASIN None visible.		
INTAKE STRUCTURE A four foot diameter concrete sluice way, with trash rack, exists at the east base of abandoned powerhouse west of west spillway. Trash rack has one bar missing and some bars are damaged. A four foot diameter concrete sluice way exists at the base of east spillway. Both sluice ways in good condition.	Repair trash rack.	
OUTLET STRUCTURE Water exits from the four foot diameter concrete sluice way at west way at west base of east spillway on to a concrete apron.		Replace valve. Repair stem stand concrete support.
OUTLET FACILITIES The rising stem sluice gate at the west sluice was inoperable. The concrete foundation supporting the valve stem was deteriorated. Water from pump house mentioned above exits through two concrete notches ($3' \frac{1}{2} \times 2' \frac{1}{2}$ & $5' \frac{1}{2} \times 3' \frac{1}{2}$) at south base of pump house into channel.		
EMERGENCY GATE Emergency spillway adjacent to east spillway.		

VISUAL EXAMINATION OF		UNGATED SPILLWAY	REMARKS AND RECOMMENDATIONS
	OBSERVATIONS		
CONCRETE WEIR See "Concrete Spillways".			
APPROACH CHANNEL Reservoir-water in reservoir was drained for current dry dredging operations.			
DISCHARGE CHANNEL Two in good condition.			
BRIDGE AND PIERS None			

<u>VISUAL EXAMINATION OF</u>	<u>GATED SPILLWAY</u>	<u>OBSERVATIONS</u>	<u>REMARKS AND RECOMMENDATIONS</u>
CONCRETE SILL N/A			
APPROACH CHANNEL N/A			
DISCHARGE CHANNEL N/A			
BRIDGE AND PIERS N/A			
GATES & OPERATION EQUIPMENT N/A			

INSTRUMENTATION		
VISUAL EXAMINATION OF MONUMENTATION/SURVEYS	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
None	OBSERVATION WELLS None	WEIRS None
		PIEZOMETERS None
		OTHER None

VISUAL EXAMINATION OF	RESERVOIR OBSERVATIONS	REMARKS AND RECOMMENDATIONS			
		SLOPES	SEDIMENTATION	STRUCTURES	WATER LEVEL
SLOPES	Water in reservoir was drained for current dry dredging operations. Moderate side slopes, no indication of slope instability.				
SEDIMENTATION	Reservoir is currently being dredged.				

VISUAL EXAMINATION OF	DOWNSTREAM CHANNEL	OBSERVATIONS	REMARKS AND RECOMMENDATIONS
			CONDITON (OBSTRUCTIONS, DEBRIS, ETC.)
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)			Condition of both channels good. A roadway bridge crosses over east channel approximately 700 feet from the east spillway.
SLOPES			2 horizontal to 1 vertical.
APPROXIMATE NUMBER OF HOMES AND POPULATION			A municipal building (Borough of Park Ridge), a recreation area and a lumber yard approximately 1200 feet from east spillway.

CHECK LIST
ENGINEERING DATA
DESIGN, CONSTRUCTION, OPERATION

ITEM	REMARKS
PLAN OF DAM	Available on microfilm at NJ Department of Environmental Protection (NJ-DEP), 1474 Prospect Street, P.O. Box CN-029 Trenton, NJ 08625
REGIONAL VICINITY MAP	Available--Bergen County Map and U.S.G.S. Quadrangle sheet for Park Ridge, New Jersey-New York
CONSTRUCTION HISTORY	No formal history exists, but it can be deduced from available plans and drawings
TYPICAL SECTIONS OF DAM	Available on microfilm at NJ-DEP
HYDROLOGIC/HYDRAULIC DATA	No hydrologic data. Hydraulic data available on microfilm at NJ-DEP
OUTLETS - PLAN	Available on microfilm (NJ-DEP)
- DETAILS	Available in microfilm (NJ-DEP)
- CONSTRAINTS	None
- DISCHARGE RATINGS	Not available
RAINFALL / RESERVOIR RECORDS	Not available

CHECK LIST
 ENGINEERING DATA
 DESIGN, CONSTRUCTION, OPERATION
 (continued)

ITEM	REMARKS
DESIGN REPORTS	None available.
GEOLOGY REPORTS	Available. U.S.G.S. Geologic Overlay Sheet for Bergen County and Engineering Soil Survey of New Jersey, Report # 4--Bergen and Hudson Counties, by Rutgers University.
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	None available
MATERIALS INVESTIGATIONS BORING RECORDS LABORATORY FIELD	None available Test boring data, dated 1946 & 1951, available on microfilm at NJ-DEP. None available None available
POST-CONSTRUCTION SURVEYS OF DAM	None
BORROW SOURCES	Unknown
SPILLWAY PLAN - SECTIONS) - DETAILS)	Available on microfilm at NJ-DEP

CHECK LIST
 ENGINEERING DATA
 DESIGN, CONSTRUCTION, OPERATION
 (continued)

ITEM	REMARKS
OPERATING EQUIPMENT PLANS AND DETAILS	None available
MONITORING SYSTEMS	None
MODIFICATIONS	Repair and reconstruction, 1952. Available on microfilm at NJ-DEP.
HIGH POOL RECORDS	Not kept
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	Inspection report for Borough of Park Ridge, Bergen County, NJ, 1978 by A.G. Lichtenstein, and Associates, Inc., Teaneck, NJ
PRIOR ACCIDENTS OF FAILURE OF DAM - DESCRIPTION - REPORT'S	Available on microfilm at NJ-DEP, which states that failure occurred during July 23, 1945 flood.
MAINTENANCE OPERATION RECORDS	None known to exist

APPENDIX B

PHOTOGRAPHS

(Taken on December 3, 1979)

Note: Water in reservoir was drained for dry dredging operations when photos were taken.

ELECTRIC LIGHT POND DAM



Photo 1 - View of West spillway from downstream. Abandoned power house is at left. Portion of earth embankment is at right.



Photo 2 - Detail showing spalling of the two buttresses, abutment and wingwall of West spillway. View is from downstream.

ELECTRIC LIGHT POND DAM




Photo 3 - View from reservoir side with dam and concrete core visible at left. The West spillway, adjacent to the abandoned power house, can be seen in center.




Photo 4 - View of retaining wall at right side of West spillway and base of abandoned tower. Note vertical crack and spalling.

ELECTRIC LIGHT POND DAM



Photo 5 - View of West spillway with reservoir on right. Note sluice way, valve and base of abandoned power house at top.



Photo 6 - Detail of sluice way at reservoir side of West spillway. Note missing bar from trash rack.

ELECTRIC LIGHT POND DAM



Photo 7 - View of the East spillway from reservoir side.
Note horizontal crack and spalling of right
abutment.



Photo 8 - View of reservoir from East spillway showing current
dredging operations.

ELECTRIC LIGHT POND DAM

Photo 9 - Detail showing spalling, exposed rebar and crack in right abutment of East spillway. Portion of emergency spillway is shown at right.



Photo 10 - Detail showing vertical crack in left abutment of East spillway and the crack across spillway.

ELECTRIC LIGHT POND DAM



Photo 11 - View of downstream channel from West spillway
(at bottom).




Photo 12 - View of East downstream channel. Sluice way water from under East spillway is shown at left and portion of emergency spillway at right.

ELECTRIC LIGHT POND DAM



Photo 13 - View of East channel, looking downstream, showing roadway bridge approximately 700 feet from the East spillway.



Photo 14 - View, looking upstream, of East and West channels merging approximately 800 feet from the East spillway. East channel is on right.

ELECTRIC LIGHT POND DAM



Photo 15 - View, looking upstream, toward East spillway on right center and portion of emergency spillway adjacent to it, on the left. Note sluiceway under East spillway. Embankment and West spillway is out of photo on viewer's left.

APPENDIX C

SUMMARY OF ENGINEERING DATA

CHECK LIST
HYDROLOGIC AND HYDRAULIC DATA
ENGINEERING DATA

Name of Dam: ELECTRIC LIGHT POND DAM

Drainage Area Characteristics: 14.2 square miles

Elevation Top Normal Pool (Storage Capacity): 132.0 NGVD (18 acre-ft.)

Elevation Top Flood Control Pool (Storage Capacity): N/A

Elevation Maximum Design Pool: 137.84 NGVD (SDF pool: 65 acre-feet)

Elevation Top Dam: 137.60 NGVD (63 acre-feet)

SPILLWAY CREST:

- a. Elevation 132.0 for east and west, 134.5 for emergency
- b. Type Ungraded concrete ogee for East & West, trapezoidal weir for emergency
- c. Width 9 ft. (east); 6 ft. (west); 12 ft. (emergency)
- d. Length 20 ft. (east), 47 ft. (west), 66 ft. (emergency)
- e. Location Spillover Not observed due to drain flow from low level pipes
Water in reservoir drained for dry dredging
- f. No. and Type of Gates None

OUTLET WORKS:

- a. Type 2-48-inch diameter low level outlet
- b. Location One located on the west of west spillway through power-house and other located at the west of east spillway
- c. Entrance Inverts 124.3 ft. (NGVD, west) 122.45 (NGVD, east)
- d. Exit Inverts 122.3 NGVD (Estimated-opening from power house)
122.07(NGVD East)
- e. Emergency Draindown Facilities 2-48-inch pipe with manual operated gate valves

HYDROMETEOROLOGICAL GAGES:


- a. Type None
- b. Location None
- c. Records None

MAXIMUM NON-DAMAGING DISCHARGE: 4,634 cfs @ 137.6 NGVD

APPENDIX D

HYDROLOGIC COMPUTATIONS

PLATE I, APPENDIX D



1 0 1 2

Scale 1" = 1 Mile

ELECTRIC LIGHT POND DAM
DRAINAGE BASIN

FREDERIC R. HARRIS, INC.

CONSULTING ENGINEERS

SUBJECT NJ DAM INSP. GROUP X
FREDERIC R. HARRIS, INC.

COMPUTED BY EKO CHECKED BY CLC

SHEET NO. 1 OF 12
JOB NO. LG-AFF-61
DATE 12/4/79

SIZE CLASSIFICATION

Surface Area of New Impoundment

7 Acre

Avg. = Depth

9 ft ±

STRUCTURAL HEIGHT OF DAM

20.6 ft

SIZE CLASSIFICATIONS

Small

Hazard Potential Classification

Potential recreation value & public safety but
Virtually no dam

Hazard Potential Classification

Low

Recommended SDF

1/2 PMF

Hydrologic Data

THE HEC-1 IS TO BE USED TO COMPUTE THE

Block Isodic Slope Method

$$C_f = 4.2 \quad 620 C_p = 520$$

(Supplied by G. Sault US Army Corps of Engineers)

D.A. = 14.25 ± mi²

FREDERIC R. HARRIS, INC. SUBJECT N.L.H. 1970 GROUP X
 CONSULTING ENGINEERS ELECTRIC LIGHT & POWER
 COMPUTED BY J.K. CHECKED BY C.L.C. SHEET NO. 2 OF 12
 JOB NO. 1-1-1 DATE 12/6/79

Precipitation

From Fig. 1E, ZONE 1 (Ref Design of Small Dam 1977)

Probable Total Precipitation = 25 in./hr. for 6 hrs.

Duration and 14.2 sq mi area

Duration (hrs)	= PMP			Value are reduced by 19.5% to
	Zone 1	Zone 6	Average	
6	96	97	96.5	
12	107	106	106.5	discon + cor
24	116.5	114	115.3	misalignment of basin
48	121.0	123	123.5	" storm intensity "

Unit Hydrograph

$$C_p = \frac{530}{640} = 0.83$$

$$t_u = C_t (L L_c)^{0.3}$$

$$= 4.3 (9.12 \times 5.05)^{0.3} = 13.57 \text{ hrs}$$

Infiltration Data


LAND USE \approx Urban \approx Residential

USE INITIAL INFILTRATION 1.5 in.
 CONSTITUENT INFILTRATION 0.15 in/hr

FREDERIC R. HARRIS, INC.
CONSULTING ENGINEERS

SUBJECT
N.J. D.A.M. INSPECTION GROUP XVII
PROJECT: ELECTRIC LIGHT & POWER
COMPUTED BY: B.K.O.P. CHECKED BY: G.L.C.

3 OF 12
SHEET NO. 3
JOB NO. LV-A-101
DATE 12/6/79



L = Length of stream = 1.12 mile
 L_c = Headstream length = 1.12 miles
the outlet at Dam Site to a point 2 miles upstream
center of gravity of the river basin

Scale 1" = 1 mile

ELECTRIC LIGHT Power Dam
PROJECT: E.L.P.D.

FREDERIC R. HARRIS, INC.
CONSULTING ENGINEERS

SUBJECT: NJ DAM INSPECTION GROUP XII
ELECTRICAL TOWER
COMPUTED BY: E.Koo CHECKED BY: C.L.C.

SHEET NO. 4 OF 12
JOB NO. 2001
DATE 12/6/79

ELEVATION - AREA - CAPACITY RELATIONSHIP

INFORMATION obtained from USGS and General plan of Reconstruction

ELE	*	124.2	132.0	137.6	140.	150
-----	---	-------	-------	-------	------	-----

Surface Area (ac)	0	7.0	2	17.9	51.9
-------------------	---	-----	---	------	------

* Weighted elev. of bottom of Lake at 140 ft

HEC-1 D12 program will assign stream concavity from
surface area and elevation.


Low Level Outlets

Electric light pond was designed with 2 sluice gates controlled 4' f concrete pipes low level outlet. Inlet pipes which are located through the end spilling and all in to the power house are prevent being used for rinsing the pond while during operation like this.

FREDERIC R. HARRIS, INC.
CONSULTING ENGINEERS

SUBJECT N.J. DAM INSP. JUN 1971 XVII
ELECTRIC LIGHT PANE
COMPUTED BY E.R.H. CHECKED BY C.L.C.

5 OF 12
SHEET NO. 5
JOB NO. 12400
DATE 12/6/70




L1	H1	H2	H3	H4	L1	L2	L3	L4	C1	C2	C3	C4	Q = C1H1 + C2H2 + C3H3 + C4H4	(ft)
134.5	2.5				67	67	67	67	1.6	1.6	1.6	1.6	100.0	100.0
134.0	4.0	1.5			67	67	67	67	2.5	2.5	2.5	2.5	203.7	424
137.7	5.6	3.1			67	67	67	67	3.6	3.6	3.6	3.6	337.9	126.0
139.0	7.0	4.5	1.4		67	67	67	67	4.0	4.0	4.0	4.0	411.5	222.2
140.0	8	5.5	2.4		67	67	67	67	5.6	5.6	5.6	5.6	576.1	294.4
150.0	11.0	15.5	12.4	11	67	67	67	67	8.0	8.0	8.0	8.0	1375.1	1000.0
													1949.3	1400.0

FREDERIC R. HARRIS, INC.
CONSULTING ENGINEERS

SUBJECT N.C. DAM NO. 2 Group 57A
ELECTRIC LIGHT POND
COMPUTED BY B.E. CHECKED BY C.L.C.

SHEET NO. 6 OF 12
JOB NO. 10483-01
DATE 12/16/79



FREDERIC R. HARRIS, INC.
CONSULTING ENGINEERS

SUBJECT N.J. 111-1457 GROUP 211
Electric light fixture
COMPUTED BY B1C CHECKED BY C.L.C.

7 OF 12
SHEET NO. 7 OF 12
JOB NO. 10-A93-31
DATE 12/7/79


50 -

40 -

% CMF
30 -

20 -

10 -



Overtopping of dam occurs at Ele. 127.6 with
 $Q = 4845 \text{ cfs}$ ($\sim 45\% \text{ CMF}$)

FREDERIC R. HARRIS, INC.
CONSULTING ENGINEERS

SUBJECT NJ Dam Inv. Group ~~XVII~~
ELECTRIC LIGHT POLE
COMPUTED BY PK

SHEET NO. 8 OF 12
JOB NO. 10-A-3
DATE 2/11/80

Sensitivity Analysis summary

Breadth	Side	Preach	fil	Initial	Fail	Max.
width	slope	bottom ele.	sim	water	elev.	Peak
40	1	126	0.5	132	137.17	5490
40	1	126	0.5	122	137.84	6381 ←
40	1	126	0.5	12	137.80	6330
40	1	126	0.5	132	137.75	6260



FREDERIC R. HARRIS, INC.
CONSULTING ENGINEERS

SUBJECT N 1 Dam Inside Group VIII
ELECTRIC LIGHT POWER
COMPUTED BY E.K. CHECKED BY C.H.C.

SHEET NO. 9 OF 12
JOB NO. 10-412-1
DATE 12/7/79

BREACH ANALYSIS


Based on Sensitivity Analysis, the breach begins to develop when the lake stage to reach elevation 137.82 with max. peak outflow (C.21 ft) over than the top of dam.



FREDERIC R. HARRIS, INC.
CONSULTING ENGINEERS

SUBJECT 1-2am T-10 Group VII
Electric Light
COMPUTED BY B.L.S. CHECKED BY C.L.C.


SHEET NO. 10 OF 12
JOB NO. 10-1513-01
DATE 2/15/80



FREDERIC R. HARRIS, INC.
CONSULTING ENGINEERS

SUBJECT: NJ Dam Safety Inspr Prog: Group SVI
ELECTRIC LIGHT & POWER
COMPUTED BY: G.K. CHECKED BY: C.L.C.

SHEET NO. 11 OF 12
JOB NO. 10-A1-1
DATE 2/19/80




FREDERIC R. HARRIS, INC.
CONSULTING ENGINEERS

SUBJECT: ~~WATER LEVELS~~
ELECTRIC LIGHT
COMPUTED BY: EK

12
SHEET NO. 12 OF 12
JOB NO.
DATE 12/16/79

Drawdown Time computation

132.00 WEST SPILLWAY 132.00 EST SPILLWAY 132



Normal Elevation TO
START 132.0
D.A. = 14.2 cm/m³
INFLOW = 2.83 m³/sec
= 20.4 CFS

Use Fig B-15 -
Design of Impoundment
for Q Ave. outlet
discharge

For Simplification, Assume we have inflow $122.5 + 121.3/2 = 122.2$ and this is not a constant value.

RES ELE	ACR	Avg Area ac.	VOLUME	AVE REC ELE	h	Q	t: hrs	CUR TIME	TIME	SPILL	SPILL
				D	AVE CHT	DISCHARGE	Vol x 24	hrs	24 hr	28.12	hrs
132	7.0		5.44	10.88	131	2.2	340	0.39	0.39	0.03	0.92
12.0	3.87		2.77	5.54	129	1.7	280	0.24	0.13	0.02	0.63
12.5	1.66		1.02	2.04	127	1.2	200	0.12	0.75	0.02	0.82
12.6	0.37		0.22	0.44	125.5	0.83	120	0.04	0.79	0.01	0.17
12.5	0.07		0.04	0.1	125.1	0.73	94	0.01	0.80	0	0.88
124.2	0				123.2						
122.2	0										

TIME OF COMPLETE DRAWDOWN WITH NO INFLOW = 0.80 hr.

TIME OF COMPLETE DRAWDOWN WITH INFLOW = 0.88 hr

$$\text{ASSUME } A_1 = \frac{A^2}{\left(\frac{h}{H_T} + 1\right)^2} \quad A_2 = 7 \text{ Acres} \quad h + H_T = 7.8$$


AD-A087 329

NEW JERSEY DEPT OF ENVIRONMENTAL PROTECTION TRENTON
NATIONAL DAM SAFETY PROGRAM, ELECTRIC LIGHT POND DAM (NJ00245) --ETC(U)
FEB 80 J TALERICO


F/G 13/13
DACPW61-79-C-0011
NI

UNCLASSIFIED

2 OF 2
AD-A087 329



END
DATE FILED
FEB 80
DTIC



N J DAM SAFETY INSPECTION PROGRAM--GROUP XVII 1048301
 N J 00245 ELECTRIC LIGHT POND, BERGEN COUNTY, NJ
 MULT RATIO ROUTING, PRC-HARRIS INC., WOODBRIDGE, NJ

	NO	NHR	NMIN	IDAY	IHR	IMIN	METRC	IPLT	IPRT	NSTAN
	150	0	30	0	0	0	0	0	1	0
			JOPER	NWT	LROPT	TRACE				
			5	0	0	0				

MULTI-PLAN ANALYSES TO BE PERFORMED
 NPLAN= 2 NRTIO= 1 LRTIO= 1

RTIOS= .50

SUB-AREA RUNOFF COMPUTATION

INFLOW HYDROGRAPH THROUGH ELECTRIC LIGHT POND

INSTAO	ICDMP	RECON	ITAPE	JPLT	JPRT	INAME	IStage	IAUTO
LAKE	0	0	0	0	0	0	0	0

HYDRO	TUH03	TAREA	SNAP	HYDROGRAPH DATA	RATIO	ISNOW	ISAME	LOCAL
1	1	14.20	0.00	14.20	.81	0.000	0	0

SPFE	PMS	R6	R12	R24	R48	R72	R96
0.00	25.00	96.50	106.50	115.30	123.50	0.00	0.00

LROPT	STRKR	DUTKR	RTIOL	ERAIN	LOSS DATA	CNSTL	ALSMX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.50	.15	0.00

UNIT HYDROGRAPH DATA
 TP= 13.60 CP= .83 NTA= 0

RECEDITION DATA
 STRTO= -1.00 QRCSEN= -.05 RTIOR= 2.00

CLARK DID NOT CONVERGE TO GIVEN SNYDER COEFFICIENTS
 APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC=38.47 AND R= 8.85 INTERVALS

UNIT HYDROGRAPH	71 END-OF-PERIOD ORDINATES, LAG= 13.46 HOURS, CP= .82 VOL= 1.00
6.	22. 44. 69. 97. 126. 155. 185. 215. 244.
274. 303. 331. 359. 387. 413. 440. 465. 490.	
534. 549. 561. 570. 575. 578. 577. 574. 569.	
552. 540. 526. 510. 491. 470. 445. 415.	
302. 270. 242. 216. 194. 173. 155. 139. 124.	
99. 89. 79. 71. 63. 57. 51. 45. 41.	
33. 29. 26. 23. 21. 19. 17. 15. 13.	
11. 11. 11. 11. 11. 11. 11. 11. 12.	

0

END-OF-PERIOD FLOW

MO.	DA	HR.	MIN	PERIOD	RAIN	EXCS	LOSS	CMPD Q
MO.	DA	HR.	MIN	PERIOD	RAIN	EXCS	LOSS	CMPD Q
1.01	1.30	1.00	0.00	1.00	0.00	0.00	0.00	410.
1.01	1.30	2.00	4.00	1.00	0.00	0.00	0.00	547.
1.01	1.30	2.00	5.00	1.00	0.00	0.00	0.00	710.
1.01	1.30	2.00	6.00	1.00	0.00	0.00	0.00	914.
1.01	1.30	2.00	7.00	1.00	0.00	0.00	0.00	1183.
1.01	1.30	2.00	8.00	1.00	0.00	0.00	0.00	1536.
1.01	1.30	2.00	9.00	1.00	0.00	0.00	0.00	1953.
1.01	1.30	3.00	4.00	1.00	0.00	0.00	0.00	2420.
1.01	1.30	3.00	5.00	1.00	0.00	0.00	0.00	2928.
1.01	1.30	3.00	6.00	1.00	0.00	0.00	0.00	3464.
1.01	1.30	3.00	7.00	1.00	0.00	0.00	0.00	4014.
1.01	1.30	3.00	8.00	1.00	0.00	0.00	0.00	4569.
1.01	1.30	3.00	9.00	1.00	0.00	0.00	0.00	5123.
1.01	1.30	4.00	5.00	1.00	0.00	0.00	0.00	5673.
1.01	1.30	4.00	6.00	1.00	0.00	0.00	0.00	6214.
1.01	1.30	4.00	7.00	1.00	0.00	0.00	0.00	6746.
1.01	1.30	4.00	8.00	1.00	0.00	0.00	0.00	7265.
1.01	1.30	4.00	9.00	1.00	0.00	0.00	0.00	7768.
1.01	1.30	5.00	6.00	1.00	0.00	0.00	0.00	8252.
1.01	1.30	5.00	7.00	1.00	0.00	0.00	0.00	8712.
1.01	1.30	5.00	8.00	1.00	0.00	0.00	0.00	9145.
1.01	1.30	5.00	9.00	1.00	0.00	0.00	0.00	9547.
1.01	1.30	6.00	7.00	1.00	0.00	0.00	0.00	9914.
1.01	1.30	6.00	8.00	1.00	0.00	0.00	0.00	10236.
1.01	1.30	6.00	9.00	1.00	0.00	0.00	0.00	10504.
1.01	1.30	7.00	8.00	1.00	0.00	0.00	0.00	10712.
1.01	1.30	7.00	9.00	1.00	0.00	0.00	0.00	10860.
1.01	1.30	8.00	9.00	1.00	0.00	0.00	0.00	10949.
1.01	1.30	9.00	10.00	1.00	0.00	0.00	0.00	10981.
1.01	1.30	10.00	11.00	1.00	0.00	0.00	0.00	10990.
1.01	1.30	10.00	12.00	1.00	0.00	0.00	0.00	10991.
1.01	1.30	10.00	13.00	1.00	0.00	0.00	0.00	10992.
1.01	1.30	10.00	14.00	1.00	0.00	0.00	0.00	10993.
1.01	1.30	10.00	15.00	1.00	0.00	0.00	0.00	10994.
1.01	1.30	10.00	16.00	1.00	0.00	0.00	0.00	10995.
1.01	1.30	10.00	17.00	1.00	0.00	0.00	0.00	10996.
1.01	1.30	10.00	18.00	1.00	0.00	0.00	0.00	10997.
1.01	1.30	10.00	19.00	1.00	0.00	0.00	0.00	10998.
1.01	1.30	10.00	20.00	1.00	0.00	0.00	0.00	10999.
1.01	1.30	10.00	21.00	1.00	0.00	0.00	0.00	11000.
1.01	1.30	10.00	22.00	1.00	0.00	0.00	0.00	11001.
1.01	1.30	10.00	23.00	1.00	0.00	0.00	0.00	11002.
1.01	1.30	10.00	24.00	1.00	0.00	0.00	0.00	11003.
1.01	1.30	10.00	25.00	1.00	0.00	0.00	0.00	11004.
1.01	1.30	10.00	26.00	1.00	0.00	0.00	0.00	11005.
1.01	1.30	10.00	27.00	1.00	0.00	0.00	0.00	11006.
1.01	1.30	10.00	28.00	1.00	0.00	0.00	0.00	11007.
1.01	1.30	10.00	29.00	1.00	0.00	0.00	0.00	11008.
1.01	1.30	10.00	30.00	1.00	0.00	0.00	0.00	11009.
1.01	1.30	10.00	31.00	1.00	0.00	0.00	0.00	11010.
1.01	1.30	10.00	32.00	1.00	0.00	0.00	0.00	11011.
1.01	1.30	10.00	33.00	1.00	0.00	0.00	0.00	11012.
1.01	1.30	10.00	34.00	1.00	0.00	0.00	0.00	11013.
1.01	1.30	10.00	35.00	1.00	0.00	0.00	0.00	11014.
1.01	1.30	10.00	36.00	1.00	0.00	0.00	0.00	11015.
1.01	1.30	10.00	37.00	1.00	0.00	0.00	0.00	11016.
1.01	1.30	10.00	38.00	1.00	0.00	0.00	0.00	11017.
1.01	1.30	10.00	39.00	1.00	0.00	0.00	0.00	11018.
1.01	1.30	10.00	40.00	1.00	0.00	0.00	0.00	11019.
1.01	1.30	10.00	41.00	1.00	0.00	0.00	0.00	11020.
1.01	1.30	10.00	42.00	1.00	0.00	0.00	0.00	11021.
1.01	1.30	10.00	43.00	1.00	0.00	0.00	0.00	11022.
1.01	1.30	10.00	44.00	1.00	0.00	0.00	0.00	11023.
1.01	1.30	10.00	45.00	1.00	0.00	0.00	0.00	11024.
1.01	1.30	10.00	46.00	1.00	0.00	0.00	0.00	11025.
1.01	1.30	10.00	47.00	1.00	0.00	0.00	0.00	11026.
1.01	1.30	10.00	48.00	1.00	0.00	0.00	0.00	11027.
1.01	1.30	10.00	49.00	1.00	0.00	0.00	0.00	11028.
1.01	1.30	10.00	50.00	1.00	0.00	0.00	0.00	11029.
1.01	1.30	10.00	51.00	1.00	0.00	0.00	0.00	11030.
1.01	1.30	10.00	52.00	1.00	0.00	0.00	0.00	11031.
1.01	1.30	10.00	53.00	1.00	0.00	0.00	0.00	11032.
1.01	1.30	10.00	54.00	1.00	0.00	0.00	0.00	11033.
1.01	1.30	10.00	55.00	1.00	0.00	0.00	0.00	11034.
1.01	1.30	10.00	56.00	1.00	0.00	0.00	0.00	11035.
1.01	1.30	10.00	57.00	1.00	0.00	0.00	0.00	11036.
1.01	1.30	10.00	58.00	1.00	0.00	0.00	0.00	11037.
1.01	1.30	10.00	59.00	1.00	0.00	0.00	0.00	11038.
1.01	1.30	10.00	60.00	1.00	0.00	0.00	0.00	11039.
1.01	1.30	10.00	61.00	1.00	0.00	0.00	0.00	11040.
1.01	1.30	10.00	62.00	1.00	0.00	0.00	0.00	11041.
1.01	1.30	10.00	63.00	1.00	0.00	0.00	0.00	11042.
1.01	1.30	10.00	64.00	1.00	0.00	0.00	0.00	11043.

1.02	8.50	45	.17	.09	.08	23.	1.03	22.00	140	0.00	0.00	0.00	585.
1.02	9.00	66	.17	.09	.08	34.	1.03	22.30	141	0.00	0.00	0.00	533.
1.02	9.30	67	.17	.09	.08	49.	1.03	23.00	142	0.00	0.00	0.00	498.
1.02	10.00	68	.17	.09	.08	66.	1.03	23.30	143	0.00	0.00	0.00	464.
1.02	10.30	69	.17	.09	.08	86.	1.04	0.00	144	0.00	0.00	0.00	433.
1.02	11.00	70	.17	.09	.08	108.	1.04	.30	145	0.00	0.00	0.00	404.
1.02	11.30	71	.17	.09	.08	134.	1.04	1.00	146	0.00	0.00	0.00	377.
1.02	12.00	72	.17	.09	.08	162.	1.04	1.30	147	0.00	0.00	0.00	352.
1.02	12.30	73	.97	.90	.08	197.	1.04	2.00	148	0.00	0.00	0.00	328.
1.02	13.00	74	.97	.90	.08	248.	1.04	2.30	149	0.00	0.00	0.00	306.
1.02	13.30	75	1.17	1.09	.08	320.	1.04	3.00	150	0.00	0.00	0.00	286.

SUM (24.85) 19.80 5.06 361385.
(631.)(503.)(128.)(10244.61)

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	10981.	10657.	7057.	2511.	361630.
CMS	311.	302.	200.	71.	10240.
INCHES		6.98	18.49	19.74	
MM		177.33	469.70	501.36	501.44
AC-FT		5285.	13997.	14941.	14943.
THOUS CU M		6519.	17266.	18430.	

HYDROGRAPH AT STA LAKE FOR PLAN 1, RTIO 1

6.	5.	5.	5.	4.	4.
7.	6.	3.	3.	2.	2.
J.	J.	3.	1.	1.	1.
2.	2.	1.	1.	1.	1.
1.	1.	1.	1.	1.	1.
0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.
1.	2.	4.	7.	11.	17.
67.	81.	99.	124.	160.	209.
768.	977.	1210.	1464.	1732.	2007.
3373.	3632.	3884.	4126.	4356.	4573.
5356.	5430.	5475.	5491.	5480.	5444.
4921.	4745.	4548.	4329.	4091.	3835.
2417.	2169.	1943.	1741.	1560.	1397.
804.	719.	643.	575.	514.	459.
267.	249.	232.	217.	202.	189.

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	5491.	5329.	3529.	180815.
CMS	155.	151.	100.	5120.
INCHES		3.49	9.25	9.87
MM		88.67	234.85	250.68
AC-FT		2642.	6999.	7471.
THOUS CU M		3259.	8633.	9215.

PLAN 2 SAME AS PLAN 1

	ROUTING DISCHARGE THROUGH DAM	HYDROGRAPH ROUTING		
1STAO	ICOMP 1	I ECON 0	ITAPE 0	JFLT 0
NAME				J PRT 0
				I NAME 0
				I STAGE 0
				I AUTO 0

ALL PLANS HAVE SAME
ROUTING DATA

		GLOSS	CLOSS	Avg	TRES	LSAME	IOP1	IFMP	LSTR
STAGE	132.00	134.50	136.00	137.30	139.00	140.00	0	0	0
FLOW	0.00	1006.00	2461.00	4634.00	9152.00	13751.00	150.00	150.00	-1
SURFACE AREA=	0.	7.	9.	18.	58.				
CAPACITY=	0.	23.	68.	99.	457.				
ELEVATION=	122.	132.	138.	140.	150.				
CREL	132.0	SFWID	CORW	EXPW	ELEV	COOL	CAREA	EXPL	
	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	
						DAM DATA			
						TOPEL	COQD	EXFD	DAMWID
						137.6	0.0	0.0	0.
BREWD	Z	DAM BREACH DATA							
40.	1.00	ELBM	TRAIL						
		WSEL	FAILEL						
		40.	50	132.00	137.87				
STATION	DAME	PLAN 1, RATIO 1							
						END-OF-PERIOD HYDROGRAPH ORDINATES			
						OUTFLOW			
						5.	5.	5.	4.
						6.	3.	2.	2.
						7.	1.	1.	1.
						8.	1.	1.	1.
						9.	0.	0.	0.
						10.	0.	0.	0.
						11.	0.	0.	0.
						12.	0.	0.	0.
						13.	0.	0.	0.
						14.	0.	0.	0.
						15.	0.	0.	0.
						16.	0.	0.	0.
						17.	0.	0.	0.
						18.	0.	0.	0.
						19.	0.	0.	0.
						20.	0.	0.	0.
						21.	0.	0.	0.
						22.	0.	0.	0.
						23.	0.	0.	0.
						24.	0.	0.	0.
						25.	0.	0.	0.
						26.	0.	0.	0.
						27.	0.	0.	0.
						28.	0.	0.	0.
						29.	0.	0.	0.
						30.	0.	0.	0.
						31.	0.	0.	0.
						32.	0.	0.	0.
						33.	0.	0.	0.
						34.	0.	0.	0.
						35.	0.	0.	0.
						36.	0.	0.	0.
						37.	0.	0.	0.
						38.	0.	0.	0.
						39.	0.	0.	0.
						40.	0.	0.	0.
						41.	0.	0.	0.
						42.	0.	0.	0.
						43.	0.	0.	0.
						44.	0.	0.	0.
						45.	0.	0.	0.
						46.	0.	0.	0.
						47.	0.	0.	0.
						48.	0.	0.	0.
						49.	0.	0.	0.
						50.	0.	0.	0.
						51.	0.	0.	0.
						52.	0.	0.	0.
						53.	0.	0.	0.
						54.	0.	0.	0.
						55.	0.	0.	0.
						56.	0.	0.	0.
						57.	0.	0.	0.
						58.	0.	0.	0.
						59.	0.	0.	0.
						60.	0.	0.	0.
						61.	0.	0.	0.
						62.	0.	0.	0.
						63.	0.	0.	0.
						64.	0.	0.	0.
						65.	0.	0.	0.
						66.	0.	0.	0.
						67.	0.	0.	0.
						68.	0.	0.	0.
						69.	0.	0.	0.
						70.	0.	0.	0.
						71.	0.	0.	0.
						72.	0.	0.	0.
						73.	0.	0.	0.
						74.	0.	0.	0.
						75.	0.	0.	0.
						76.	0.	0.	0.
						77.	0.	0.	0.
						78.	0.	0.	0.
						79.	0.	0.	0.
						80.	0.	0.	0.
						81.	0.	0.	0.
						82.	0.	0.	0.
						83.	0.	0.	0.
						84.	0.	0.	0.
						85.	0.	0.	0.
						86.	0.	0.	0.
						87.	0.	0.	0.
						88.	0.	0.	0.
						89.	0.	0.	0.
						90.	0.	0.	0.
						91.	0.	0.	0.
						92.	0.	0.	0.
						93.	0.	0.	0.
						94.	0.	0.	0.
						95.	0.	0.	0.
						96.	0.	0.	0.
						97.	0.	0.	0.
						98.	0.	0.	0.
						99.	0.	0.	0.
						100.	0.	0.	0.
						101.	0.	0.	0.
						102.	0.	0.	0.
						103.	0.	0.	0.
						104.	0.	0.	0.
						105.	0.	0.	0.
						106.	0.	0.	0.
						107.	0.	0.	0.
						108.	0.	0.	0.
						109.	0.	0.	0.
						110.	0.	0.	0.
						111.	0.	0.	0.
						112.	0.	0.	0.
						113.	0.	0.	0.
						114.	0.	0.	0.
						115.	0.	0.	0.
						116.	0.	0.	0.
						117.	0.	0.	0.
						118.	0.	0.	0.
						119.	0.	0.	0.
						120.	0.	0.	0.
						121.	0.	0.	0.
						122.	0.	0.	0.
						123.	0.	0.	0.
						124.	0.	0.	0.
						125.	0.	0.	0.
						126.	0.	0.	0.
						127.	0.	0.	0.
						128.	0.	0.	0.
						129.	0.	0.	0.
						130.	0.	0.	0.
						131.	0.	0.	0.
						132.	0.	0.	0.
						133.	0.	0.	0.
						134.	0.	0.	0.
						135.	0.	0.	0.
						136.	0.	0.	0.
						137.	0.	0.	0.
						138.	0.	0.	0.
						139.	0.	0.	0.
						140.	0.	0.	0.
						141.	0.	0.	0.
						142.	0.	0.	0.
						143.	0.	0.	0.
						144.	0.	0.	0.
						145.	0.	0.	0.
						146.	0.	0.	0.
						147.	0.	0.	0.
						148.	0.	0.	0.
						149.	0.	0.	0.
						150.	0.	0.	0.
						151.	0.	0.	0.
						152.	0.	0.	0.
						153.	0.	0.	0.
						154.	0.	0.	0.
						155.	0.	0.	0.
						156.	0.	0.	0.
						157.	0.	0.	0.
						158.	0.	0.	0.
						159.	0.	0.	0.
						160.	0.	0.	0.
						161.	0.	0.	0.
						162.	0.	0.	0.
						163.	0.	0.	0.
						164.	0.	0.	0.
						165.	0.	0.	0.
						166.	0.	0.	0.
						167.	0.	0.	0.
						168.	0.	0.	0.
						169.	0.	0.	0.
						170.	0.	0.	0.
						171.	0.	0.	0.
						172.	0.	0.	0.
						173.	0.	0.	0.
						174.	0.	0.	0.
						175.	0.	0.	0.
						176.	0.	0.	0.
						177.	0.	0.	0.
						178.	0.	0.	0.
						179.	0.	0.	0.
						180.	0.	0.	0.
						181.	0.	0.	0.
						182.	0.	0.	0.
						183.	0.	0.	0.

18

PEAK OUTFLOW IS 5490. AT TIME 52.00 HOURS

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	\$490.	5328.	3528.	1255.	180756.
CMS	155.	151.	100.	36.	5118.
INCHES		3.49	9.24	9.87	9.87
MM		88.65	234.81	250.60	250.64
AC-FT		2642.	6998.	7468.	7468.
THOUS CU M		3259.	8631.	9212.	9213.

DAM BREACH DATA			WSEL	F4
BWRID	Z	ELBM		
40.	1.00	126.00	.50	132.00
STATION NAME, PLAN 2, RATIO 1				

	650.00	130.00	950.00	120.00	1268.00	115.00	1	.00	109.00	1320.00	109.00
	\$32.00	115.00	1550.00	120.00	1420.00	130.00					
SINKAGE	0.00	1.18	2.48	3.90	5.45	7.12	9.44	14.77	23.41		35.35
	50.60	67.97	86.48	106.14	126.93	148.87	171.95	196.17	221.53		248.03
OUTFLOW	0.00	129.86	418.71	837.91	1380.25	2044.14	2912.13	4131.64	5830.06		8142.37
	11201.54	15361.10	20293.25	25990.66	32455.25	39694.27	4718.30	56540.07	66173.75		76634.58
STAGE	109.00	110.11	111.21	112.32	113.42	114.53	115.63	116.74	117.84		118.95
	120.05	121.16	122.26	123.37	124.47	125.58	126.68	127.79	128.89		130.00
FLOW	0.00	129.86	418.71	837.91	1380.25	2044.14	2912.13	4131.64	5830.06		8142.37
	11201.54	15361.10	20293.25	25990.66	32455.25	39694.27	4718.30	56540.07	66173.75		76634.58

STATION REACH1, PLAN 1, RTIO 1

21

	PEAK CFS	6-HOUR CHS	24-HOUR INCHES	72-HOUR MM	TOTAL MM	VOLUME
110.6	110.5	110.5	110.	110.4	110.3	110.2
110.7	5490. 155.	5328. 151.	3528. 100.	1255. 36.	18072. 5118.	
	INCHES					
	MH	3.49	9.24	9.86	9.87	
	AC-F	89.65	234.80	250.56	250.60	
	THOUS CU M	2642.	6997.	7467.	7468.	
		3259.	8631.	9210.	9212.	

MAXIMUM STAGE IS 117.6

MAXIMUM STORAGE - 22.

STATION	REACH1, PLAN 2, RTD1 1									
	OUTFLOW					STOR				
	5.	5.	5.	5.	5.	5.	5.	5.	5.	STAGE
1	3	3	3	3	3	3	3	3	3	109.1
2	2	2	2	2	2	2	2	2	2	109.0
3	1	1	1	1	1	1	1	1	1	109.0
4	0	0	0	0	0	0	0	0	0	109.0
5	0	0	0	0	0	0	0	0	0	109.0
6	1	2	3	4	5	6	7	8	9	109.0
7	2	3	4	5	6	7	8	9	10	109.0
8	3	4	5	6	7	8	9	10	11	109.0
9	4	5	6	7	8	9	10	11	12	109.0
10	5	6	7	8	9	10	11	12	13	109.0
11	6	7	8	9	10	11	12	13	14	109.0
12	7	8	9	10	11	12	13	14	15	109.0
13	8	9	10	11	12	13	14	15	16	109.0
14	9	10	11	12	13	14	15	16	17	109.0
15	10	11	12	13	14	15	16	17	18	109.0
16	11	12	13	14	15	16	17	18	19	109.0
17	12	13	14	15	16	17	18	19	20	109.0
18	13	14	15	16	17	18	19	20	21	109.0
19	14	15	16	17	18	19	20	21	22	109.0
20	15	16	17	18	19	20	21	22	23	109.0
21	16	17	18	19	20	21	22	23	24	109.0
22	17	18	19	20	21	22	23	24	25	109.0
23	18	19	20	21	22	23	24	25	26	109.0
24	19	20	21	22	23	24	25	26	27	109.0
25	20	21	22	23	24	25	26	27	28	109.0
26	21	22	23	24	25	26	27	28	29	109.0
27	22	23	24	25	26	27	28	29	30	109.0
28	23	24	25	26	27	28	29	30	31	109.0
29	24	25	26	27	28	29	30	31	32	109.0
30	25	26	27	28	29	30	31	32	33	109.0
31	26	27	28	29	30	31	32	33	34	109.0
32	27	28	29	30	31	32	33	34	35	109.0
33	28	29	30	31	32	33	34	35	36	109.0
34	29	30	31	32	33	34	35	36	37	109.0
35	30	31	32	33	34	35	36	37	38	109.0
36	31	32	33	34	35	36	37	38	39	109.0
37	32	33	34	35	36	37	38	39	40	109.0
38	33	34	35	36	37	38	39	40	41	109.0
39	34	35	36	37	38	39	40	41	42	109.0
40	35	36	37	38	39	40	41	42	43	109.0
41	36	37	38	39	40	41	42	43	44	109.0
42	37	38	39	40	41	42	43	44	45	109.0
43	38	39	40	41	42	43	44	45	46	109.0
44	39	40	41	42	43	44	45	46	47	109.0
45	40	41	42	43	44	45	46	47	48	109.0
46	41	42	43	44	45	46	47	48	49	109.0
47	42	43	44	45	46	47	48	49	50	109.0
48	43	44	45	46	47	48	49	50	51	109.0
49	44	45	46	47	48	49	50	51	52	109.0
50	45	46	47	48	49	50	51	52	53	109.0
51	46	47	48	49	50	51	52	53	54	109.0
52	47	48	49	50	51	52	53	54	55	109.0
53	48	49	50	51	52	53	54	55	56	109.0
54	49	50	51	52	53	54	55	56	57	109.0
55	50	51	52	53	54	55	56	57	58	109.0
56	51	52	53	54	55	56	57	58	59	109.0
57	52	53	54	55	56	57	58	59	60	109.0
58	53	54	55	56	57	58	59	60	61	109.0
59	54	55	56	57	58	59	60	61	62	109.0
60	55	56	57	58	59	60	61	62	63	109.0
61	56	57	58	59	60	61	62	63	64	109.0
62	57	58	59	60	61	62	63	64	65	109.0
63	58	59	60	61	62	63	64	65	66	109.0
64	59	60	61	62	63	64	65	66	67	109.0
65	60	61	62	63	64	65	66	67	68	109.0
66	61	62	63	64	65	66	67	68	69	109.0
67	62	63	64	65	66	67	68	69	70	109.0
68	63	64	65	66	67	68	69	70	71	109.0
69	64	65	66	67	68	69	70	71	72	109.0
70	65	66	67	68	69	70	71	72	73	109.0
71	66	67	68	69	70	71	72	73	74	109.0
72	67	68	69	70	71	72	73	74	75	109.0
73	68	69	70	71	72	73	74	75	76	109.0
74	69	70	71	72	73	74	75	76	77	109.0
75	70	71	72	73	74	75	76	77	78	109.0
76	71	72	73	74	75	76	77	78	79	109.0
77	72	73	74	75	76	77	78	79	80	109.0
78	73	74	75	76	77	78	79	80	81	109.0
79	74	75	76	77	78	79	80	81	82	109.0
80	75	76	77	78	79	80	81	82	83	109.0
81	76	77	78	79	80	81	82	83	84	109.0
82	77	78	79	80	81	82	83	84	85	109.0
83	78	79	80	81	82	83	84	85	86	109.0
84	79	80	81	82	83	84	85	86	87	109.0
85	80	81	82	83	84	85	86	87	88	109.0
86	81	82	83	84	85	86	87	88	89	109.0
87	82	83	84	85	86	87	88	89	90	109.0
88	83	84	85	86	87	88	89	90	91	109.0
89	84	85	86	87	88	89	90	91	92	109.0
90	85	86	87	88	89	90	91	92	93	109.0
91	86	87	88	89	90	91	92	93	94	109.0
92	87	88	89	90	91	92	93	94	95	109.0
93	88	89	90	91	92	93	94	95	96	109.0
94	89	90	91	92	93	94	95	96	97	109.0
95	90	91	92	93	94	95	96	97	98	109.0
96	91	92	93	94	95	96	97	98	99	109.0
97	92	93	94	95	96	97	98	99	100	109.0
98	93	94	95	96	97	98	99	100	101	109.0
99	94	95	96	97	98	99	100	101	102	109.0
100	95	96	97	98	99	100	101	102	103	109.0
101	96	97	98	99	100	101	102	103	104	109.0
102	97	98	99	100	101	102	103	104	105	109.0
103	98	99	100	101	102	103	104	105	106	109.0
104	99	100	101	102	103	104	105	106	107	109.0
105	100	101	102	103	104	105	106	107	108	109.0
106	101	102	103	104	105	106	107	108	109	109.0
107	102	103	104	105	106	107	108	109	110	109.0
108	103	104	105	106	107	108	109	110	111	109.0
109	104	105	106	107	108	109	110	111	112	109.0
110	105	106	107	108	109	110	111	112	113	109.0
111	106	107	108	109	110	111	112	113	114	109.0
112	107	108	109	110	111	112	113	114	115	109.0
113	108	109	110	111	112	113	114	115	116	109.0
114	109	110	111	112	113	114	115	116	117	109.0
115	110	111	112	113	114	115	116	117	118	109.0
116	111	112	113	114	115	116	117	118	119	109.0
117	112	113	114	115	116	117	118	119	120	109.0
118	113	114	115	116	117	118	119	120	121	109.0
119	114	115	116	117	118	119	120	121	122	109.0
120	115	116	117	118	119	120	121	122	123	109.0
121	116	117	118	119	120	121	122	123	124	109.0
122	117	118	119	120	121	122	123	124	125	109.0
123	118	119	120	121	122	123	124	125	126	109.0
124	119	120	121	122	123	124	125	126	127	109.0
125	120	121	122	123	124	125	126	127	128	109.0
126	121	122	123	124	125	126	127	128	129	109.0
127	122	123	124	125	126	127	128	129	130	109.0
128	123	124	125	126	127	128	129	130	131	109.0
129	124	125	126	127	128	129	130	131	132	109.0
130	125	126	127	128	129	130	131	132	133	109.0
131	126	127	128	129	130	131	132	133	134	109.0
132	127	128	129	130	131	132	133	134	135	109.0
133	128	129	130	131	132	133	134	135	136	109.0
134	129	130	131	132	133	134	135	136	137	109.0
135	130	131	132	133	134	135	136	137	138	109.0
136	131	132	133	134	135	136	137	138	139	109.0
137	132	133	134							

115.1	114.8	114.5	114.1	113.8	113.5	113.2	113.0	112.7	112.5
112.4	112.1	111.9	111.7	111.5	111.4	111.3	111.1	110.9	110.8
110.7	110.6	110.5	110.5	110.4	110.4	110.3	110.3	110.2	110.2
CFS	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME				
CMS	5490.	5328.	3528.	1255.	180727.				
INCHES	155.	151.	100.	36.	518.				
MM		3.49	9.24	9.86	9.87				
AC-FT		88.65	234.80	250.56	250.60				
THOUS CU M		2642.	6997.	7467.	7468.				
		3259.	8631.	9210.	9212.				

MAXIMUM STORAGE = 22.

MAXIMUM STAGE IS 117.6

1

**PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
AREA IN SQUARE MILES (SQUARE KILOMETERS)**

OPERATION	STATION	AREA	PLAN	RATIO	1	RATIOS APPLIED TO FLOWS
					.50	

HYDROGRAPH AT	LAKE	14.20	1	5491.
	(36.78)	(155.48)(
			2	5491.
			(155.48)(

ROUTED TO	NAME	14.20	1	5490.
	(36.78)	(155.47)(
			2	5490.
			(155.47)(

ROUTED TO	REACH1	14.20	1	5490.
	(36.78)	(155.45)(
			2	5490.
			(155.45)(

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
	STORAGE	132.00	132.00	137.60
	OUTFLOW	.23.	.23.	.4634.
		0.	0.	
RATIO OF PMF	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM OUTFLOW AC-FT	URATION OVER TOP CFS HOURS
.50	137.67	.27	71.	52.00
				0.00

PLAN 2		ELEVATION STORAGE OUTFLOW	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
RATIO OF RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS
.50	137.87	.27	71.	5490.	8.00
PLAN 1 STATION REACH1					
RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS		
.50	5490.	117.6	52.00		
PLAN 2 STATION REACH1					
RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS		
.50	5490.	117.6	52.00		

N J DAM SAFETY INSPECTION PROGRAM--GROUP XVII, 10A8301
 N J 00245 ELECTRIC LIGHT FOND, BERGEN COUNTY, NJ
 MULT RATIO ROUTING, PRC-HARRIS INC., WOODBRIDGE, N J

A1								
A2								
A3								
B	150	0						
B1	5							
J	2	1	1					
J1	.5	4	.3	.2	.1			
K	0	LAKE						
K1	1	INFLOW HYDROGRAPH THROUGH ELECTRIC LIGHT POND	0	1				
H	1	1	14.2	14.2	0.805			
P	25	25	96.5	106.5	115.3	123.5		
T							1.5	0.15
U	13.6	0.83						
X	-1	-0.05	2					
K1	1	DAM	ROUTING DISCHARGE THROUGH DAM	0	1			
Y	1		1	1				
Y1	1	134.5	136	137.6	139	140	-132	-1
Y5	132	100.6	2461	4634	9152	13751	102409	
Y5	0	0	7	9	17.5	57.9		
SE	122.0	132	137.6	140	150			
S	132							
60	137.6							
9B	40	1	126	0.5	132	137.84		
9B	40	1	126	0.5	132	200		
K	1	REACH1						
K1	U/S OF PARK AVE.	PARK RIDGE, N J	1	1				
Y1	1							
Y6	0.1	0.05	0.1	109	130	1100	0.0083	-1
Y7	650	130	950	120	1268	115	1280	109
Y7	13332	115	1550	120	1620	130		1320
K	99							

N J DAM SAFETY INSPECTION PROGRAM—GROUP XVII 10AB301
N J 00245 ELECTRIC LIGHT FOND, BERGEN COUNTY, N.J.
MULTI RATION ROUTING PC-HARBS TNC - MODERATE

NO	NHR	JOB SPECIFICATION			METRC	IPLT	IPRT	INSTAN
		NMIN	IDAY	IHR				
150	0	30	0	0	0	0	0	0
					NWT	LROPT	TRACE	
					5	0	0	0

MULTI-PLAN ANALYSES TO BE PERFORMED
NFLAN= 2 NRTID= 1 LRTID= 1

SUB-AREA RUNDOWN COMPUTATION

INFLOW HYDROGRAPH THROUGH ELECTRIC LIGHT POND

IHYG	IUNG	TAKEA	SNAP	HYDROGRAPH	DATA	RATIO	ISNOW	ISAME	LOCAL
ISTAO LAKE	ICOMP 0	IECON 0	ITAPE 0	JPLT 0	JPT	I NAME 0	1	0	IAUTO 0

SPF E	PMS	PRECIP DATA					
		R6	R12	R24	R48	R72	R96
0.00	25.00	96.50	106.50	115.30	123.50	0.00	0.00

STN#R 0.00 INT#R 0.00 RTIDL 1.00 ERAIN 0.00 LSS#RAIA 0.00 STRTK 1.00 CNSTL .15 ALSMX 0.00 RTIMP 0.00

PRECESSION DATA

INF-PROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE $T_C = 38.47$ AND $R = 8.85$ INTERVALS

UNIT	HYDROGRAPH	71	END-OF-PERIOD	ORDINATES,	LAG=	13.46	HOURS,	CP=	.82	VOL=	1.00
6.	22.	44.	69.	97.	126.	155.	185.	215.	244.	244.	244.
2274.	303.	331.	359.	387.	413.	440.	465.	490.	514.	514.	514.
334.	549.	561.	570.	575.	578.	577.	574.	569.	562.	562.	562.
552.	540.	526.	510.	491.	470.	445.	415.	378.	330.	330.	330.
502.	270.	242.	216.	194.	173.	155.	139.	124.	111.	111.	111.
89.	89.	79.	71.	63.	57.	51.	45.	41.	36.	36.	36.
33.	29.	26.	23.	21.	19.	17.	15.	13.	12.	12.	12.

END-OF-PERIOD EMISSION

NO. DA	HR. MN	PERIOD	COMP Q			EXCS			LOSS			COMP Q			
			MO.	DA	HR.	MIN	PERIOD	MO.	DA	HR.	MIN	PERIOD	MO.	DA	HR.
1. 01	.40		00	00	00	00	13	1. 02	14	00	00	76	1. 17	1. 09	00
1. 01	1.00	2	00	00	00	00	12	1. 02	14	30	00	77	1. 46	1. 38	08
1. 01	1.30	3	00	00	00	00	11	1. 02	15	00	00	78	1. 46	1. 38	08
1. 01	2.00	4	00	00	00	00	10	1. 02	15	30	00	79	1. 77	1. 70	08
1. 01	2.30	5	00	00	00	00	9	1. 02	16	00	00	80	5. 61	5. 53	08
1. 01	3.00	6	00	00	00	00	8	1. 02	16	30	00	81	1. 36	1. 28	08
1. 01	3.30	7	00	00	00	00	7	1. 02	17	00	00	82	1. 36	1. 28	08
1. 01	4.00	8	00	00	00	00	6	1. 02	17	30	00	83	1. 07	. 99	08
1. 01	4.30	9	00	00	00	00	5	1. 02	18	00	00	84	1. 07	. 99	08
1. 01	5.00	10	00	00	00	00	4	1. 02	18	30	00	85	. 09	. 01	08
1. 01	5.30	11	00	00	00	00	3	1. 02	19	00	00	86	. 09	. 01	08
1. 01	6.00	12	00	00	00	00	2	1. 02	19	30	00	87	. 09	. 01	08
1. 01	6.30	13	01	00	00	01	1	1. 02	20	00	00	88	. 09	. 01	08
1. 01	7.00	14	01	00	00	01	0	1. 02	20	30	00	89	. 09	. 01	08
1. 01	7.30	15	01	00	00	01	5	1. 02	21	00	00	90	. 09	. 01	08
1. 01	8.00	16	01	00	00	01	4	1. 02	21	30	00	91	. 09	. 01	08
1. 01	8.30	17	01	00	00	01	3	1. 02	22	00	00	92	. 09	. 01	08
1. 01	9.00	18	01	00	00	01	2	1. 02	22	30	00	93	. 09	. 01	08
1. 01	9.30	19	01	00	00	01	1	1. 02	23	00	00	94	. 09	. 01	08
1. 01	10.00	20	01	00	00	01	0	1. 02	23	30	00	95	. 09	. 01	08
1. 01	10.30	21	01	00	00	01	3	1. 03	0	00	00	96	. 09	. 01	08
1. 01	11.00	22	01	00	00	01	2	1. 03	3	00	00	97	0. 00	0. 00	0945.
1. 01	11.30	23	01	00	00	01	1	1. 03	3	00	00	98	0. 00	0. 00	0947.
1. 01	12.00	24	01	00	00	01	0	1. 03	3	00	00	99	0. 00	0. 00	0914.
1. 01	12.30	25	01	00	00	01	5	1. 03	2	00	00	100	0. 00	0. 00	08252.
1. 01	13.00	26	02	00	00	01	4	1. 03	2	30	00	101	0. 00	0. 00	08712.
1. 01	13.30	27	02	00	00	01	3	1. 03	2	30	00	102	0. 00	0. 00	0824.
1. 01	14.00	28	02	00	00	01	2	1. 03	3	00	00	103	0. 00	0. 00	0860.
1. 01	14.30	29	02	00	00	01	1	1. 03	3	00	00	104	0. 00	0. 00	08949.
1. 01	15.00	30	02	00	00	01	0	1. 03	4	00	00	105	0. 00	0. 00	08988.
1. 01	15.30	31	02	00	00	01	13	1. 03	2	20	00	106	0. 00	0. 00	0888.
1. 01	16.00	32	02	00	00	01	40	1. 03	2	20	00	107	0. 00	0. 00	0888.
1. 01	16.30	33	02	00	00	01	10	1. 03	6	00	00	108	0. 00	0. 00	08605.
1. 01	17.00	34	02	00	00	01	10	1. 03	6	30	00	109	0. 00	0. 00	0897.
1. 01	17.30	35	02	00	00	01	8	1. 03	7	00	00	110	0. 00	0. 00	0843.
1. 01	18.00	36	02	00	00	01	13	1. 03	7	30	00	111	0. 00	0. 00	0842.
1. 01	18.30	37	02	00	00	01	40	1. 03	8	00	00	112	0. 00	0. 00	0841.
1. 01	19.00	38	02	00	00	01	10	1. 03	8	30	00	113	0. 00	0. 00	0840.
1. 01	19.30	39	02	00	00	01	1	1. 03	9	00	00	114	0. 00	0. 00	08638.
1. 01	20.00	40	02	00	00	01	0	1. 03	9	30	00	115	0. 00	0. 00	08182.
1. 01	20.30	41	02	00	00	01	1	1. 03	10	00	00	116	0. 00	0. 00	0870.
1. 01	21.00	42	02	00	00	01	0	1. 03	10	30	00	117	0. 00	0. 00	08121.
1. 01	21.30	43	02	00	00	01	1	1. 03	11	00	00	118	0. 00	0. 00	08533.
1. 01	22.00	44	02	00	00	01	0	1. 03	11	30	00	119	0. 00	0. 00	08938.
1. 01	22.30	45	02	00	00	01	1	1. 03	12	00	00	120	0. 00	0. 00	08370.
1. 01	23.00	46	02	00	00	01	0	1. 03	12	30	00	121	0. 00	0. 00	0835.
1. 01	23.30	47	02	00	00	01	1	1. 03	13	00	00	122	0. 00	0. 00	0838.
1. 02	0. 00	48	02	00	00	01	0	1. 03	13	30	00	123	0. 00	0. 00	08887.
1. 02	0. 30	49	02	00	00	01	6	1. 03	14	00	00	124	0. 00	0. 00	08482.
1. 02	1. 00	50	02	00	00	06	0	1. 03	14	30	00	125	0. 00	0. 00	08007.
1. 02	1. 30	51	02	00	00	06	1	1. 03	15	00	00	126	0. 00	0. 00	08794.
1. 02	2. 00	52	02	00	00	06	1	1. 03	15	30	00	127	0. 00	0. 00	08503.
1. 02	2. 30	53	02	00	00	06	1	1. 03	16	00	00	128	0. 00	0. 00	08242.
1. 02	3. 00	54	02	00	00	06	1	1. 03	16	30	00	129	0. 00	0. 00	08007.
1. 02	3. 30	55	02	00	00	06	1	1. 03	17	00	00	130	0. 00	0. 00	08119.
1. 02	4. 00	56	02	00	00	06	1	1. 03	17	30	00	131	0. 00	0. 00	08182.
1. 02	4. 30	57	02	00	00	06	1	1. 03	18	00	00	132	0. 00	0. 00	08168.
1. 02	5. 00	58	02	00	00	06	1	1. 03	18	30	00	133	0. 00	0. 00	081439.
1. 02	5. 30	59	02	00	00	06	1	1. 03	19	00	00	134	0. 00	0. 00	081286.
1. 02	6. 00	60	02	00	00	06	1	1. 03	19	30	00	135	0. 00	0. 00	081150.
1. 02	6. 30	61	02	00	00	06	1	1. 03	20	00	00	136	0. 00	0. 00	081028.
1. 02	7. 00	62	02	00	00	06	1	1. 03	20	30	00	137	0. 00	0. 00	08118.
1. 02	7. 30	63	02	00	00	06	1	1. 03	21	00	00	138	0. 00	0. 00	08821.
1. 02	8. 00	64	02	00	00	06	1	1. 03	21	30	00	139	0. 00	0. 00	08733.

1.02	8.30	65	.17	.09	.08	23.	1.03	22.00	140	0.00	0.00	0.00	585.
1.02	9.00	66	.17	.09	.08	34.	1.03	22.30	141	0.00	0.00	0.00	533.
1.02	9.30	67	.17	.09	.08	49.	1.03	23.00	142	0.00	0.00	0.00	490.
1.02	10.00	68	.17	.09	.08	66.	1.03	23.30	143	0.00	0.00	0.00	464.
1.02	10.30	69	.17	.09	.08	86.	1.04	0.00	144	0.00	0.00	0.00	433.
1.02	11.00	70	.17	.09	.08	108.	1.04	0.30	145	0.00	0.00	0.00	404.
1.02	11.30	71	.17	.09	.08	134.	1.04	1.00	146	0.00	0.00	0.00	377.
1.02	12.00	72	.17	.09	.08	162.	1.04	1.30	147	0.00	0.00	0.00	352.
1.02	12.30	73	.97	.90	.08	197.	1.04	2.00	148	0.00	0.00	0.00	328.
1.02	13.00	74	.97	.90	.08	248.	1.04	2.30	149	0.00	0.00	0.00	306.
1.02	13.30	75	1.17	1.09	.08	320.	1.04	3.00	150	0.00	0.00	0.00	286.

SUM 24.85 19.80 5.04 361785.
(631.) (503.) (128.) (10244.61)

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	10981.	10657.	7057.	2511.	361630.
CMS	311.	302.	200.	71.	10240.
INCHES		6.98	18.49	19.74	19.74
MM		177.33	469.70	501.36	501.44
AC-FT		5285.	13997.	14941.	14943.
THOUS CU M		6519.	17266.	16430.	16432.

HYDROGRAPH AT STA LAKE FOR PLAN 1, RT10.1

6.	5.	5.	5.	4.	4.	4.	4.
3.	3.	3.	2.	2.	2.	2.	2.
2.	2.	1.	1.	1.	1.	1.	1.
1.	1.	1.	1.	1.	1.	1.	1.
0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.
1.	2.	4.	7.	11.	17.	24.	33.
67.	81.	99.	124.	160.	209.	273.	335.
768.	977.	1210.	1464.	1732.	2007.	2285.	2562.
3373.	3632.	3884.	4126.	4356.	4573.	4774.	5036.
5356.	5430.	5475.	5491.	5480.	5444.	5394.	5302.
4921.	4743.	4548.	4329.	4091.	3835.	3560.	3267.
2417.	2169.	1943.	1741.	1560.	1397.	1251.	1121.
804.	719.	643.	575.	514.	459.	410.	367.
267.	249.	232.	217.	202.	189.	176.	164.

CFS	5491.	5329.	3529.	1255.	180815.
CMS	155.	151.	100.	36.	5120.
INCHES		3.49	9.25	9.87	9.87
MM		88.67	234.85	250.68	250.72
AC-FT		2642.	6999.	7471.	7472.
THOUS CU M		3259.	6633.	9215.	9216.

PLAN 2 SAME AS PLAN 1

ROUTING DISCHARGE THROUGH DAM

HYDROGRAPH ROUTING

ISTAO NAME	ICOMP 1	IICON 0	ITAPE 0	JPLT 0	JPT	INAME 0	INSTAGE 1	IAUTO 0	IAUTO 0
---------------	------------	------------	------------	-----------	-----	------------	--------------	------------	------------

ALL PLANS HAVE SAME
ROUTING DATA

	WLOSS	ULoss	Avg	IRES	1-4E	IUPV	IFMP	LSTR
	0.0	0.000	0.00	1	1	0	0	0
	NSTFS	NSTBL	LAG	AMSKK	X	TSK	S10RA	ISPRAT
STAGE	132.00	134.50	136.00	137.60	139.00	140.00	150.00	
FLOW	0.00	1006.00	2461.00	4634.00	9152.00	13751.00	102409.00	
SURFACE AREA=	0.	7.	9.	18.	58.			
CAPACITY=	0.	23.	68.	99.	457.			
ELEVATION=	122.	132.	138.	140.	150.			
	CREL	SPWID	CORW	EXPW	ELEV	COAL	CAREA	EXPL
	132.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

BRWID	DAM BREACH DATA			WSEL	FAILEL
	Z	ELBM	TFAIL		
40.	1.00	126.00	.50	132.00	137.84
	SATION	DAME,	PLAN 1,	PLAN 1,	RATIO 1

REGIN DAN FAILURE AT 51.00 HOURS

END-OF-PERIOD HYDROGRAPH ORDINATES

PEAK OUTFLOW IS		6381. AT TIME		51.50 HOURS	
CFS	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CMS	6381.	5405.	3550.	1261.	181629.
INCHES	181.	101.	36.	5143.	
MM		3.54	9.30	9.91	9.92
AC-FT		89.93	236.27	251.81	251.85
THOUS CU M		2680.	7041.	7504.	7505.
		3306.	8685.	9256.	9258.

THE DAM BREACH HYDROGRAPH WAS DEVELOPED USING A TIME INTERVAL OF .010 HOURS DURING BREACH FORMATION.

DOWNSTREAM CALCULATIONS WILL USE A TIME INTERVAL OF .500 HOURS.
THIS TABLE COMPARES THE HYDROGRAPH FOR DOWNSTREAM CALCULATIONS WITH THE COMPUTED BREACH HYDROGRAPH.
INTERMEDIATE FLOWS ARE INTERPOLATED FROM END-OF-PERIOD VALUES.

TIME FROM INTERPOLATED BREACH HYDROGRAPH (HOURS)	COMPUTED BREACH HYDROGRAPH (CFS)		ACCUMULATED ERROR (AC-FT)	
	TIME BEGINNING OF BREACH (HOURS)	HYDROGRAPH (CFS)	ERROR (CFS)	ACCUMULATED ERROR (AC-FT)
51.000	0.000	5425.	0.	0.
51.010	.010	5445.	-18.	-18.
51.020	.020	5464.	-21.	-39.
51.030	.030	5483.	-23.	-62.
51.040	.040	5502.	-26.	-88.
51.050	.050	5521.	-27.	-115.
51.060	.060	5540.	-27.	-142.
51.070	.070	5559.	-26.	-167.
51.080	.080	5578.	-24.	-191.
51.090	.090	5597.	-20.	-211.
51.100	.100	5617.	-16.	-227.
51.110	.110	5636.	-11.	-238.
51.120	.120	5655.	-4.	-242.
51.130	.130	5674.	3.	-240.
51.140	.140	5693.	10.	-229.
51.150	.150	5712.	19.	-210.
51.160	.160	5731.	28.	-182.
51.170	.170	5750.	38.	-144.
51.180	.180	5769.	23.	-121.
51.190	.190	5789.	-7.	-128.
51.200	.200	5808.	-31.	-159.
51.210	.210	5827.	-50.	-208.
51.220	.220	5846.	5911.	-273.
51.230	.230	5865.	5942.	-350.
51.240	.240	5884.	5970.	-436.
51.250	.250	5903.	5976.	-529.

51.260	260	5922.
51.270	270	5941.
51.280	280	5961.
51.290	290	5980.
51.300	300	5999.
51.310	310	6018.
51.320	320	6037.
51.330	330	6056.
51.340	340	6075.
51.350	350	6094.
51.360	360	6113.
51.370	370	6133.
51.380	380	6152.
51.390	390	6171.
51.400	400	6190.
51.410	410	6209.
51.420	420	6228.
51.430	430	6247.
51.440	440	6266.
51.450	450	6285.
51.460	460	6305.
51.470	470	6324.
51.480	480	6343.
51.490	490	6362.
51.500	500	6381.

180W 4

TIME (HRS) (0) INTERPOLATED BREACH HYDROGRAPH

(8) COMPUTED BREACH HYDROGRAPH

TIME (HRS)	5400.	5500.	5600.	5700.	5800.	5900.
51.00	1.	0 B	0 B	0 B	0 B	0 B
51.01	2.	0 B	0 B	0 B	0 B	0 B
51.02	3.	0 B	0 B	0 B	0 B	0 B
51.03	4.	0 B	0 B	0 B	0 B	0 B
51.04	5.	0 B	0 B	0 B	0 B	0 B
51.05	6.	0 B	0 B	0 B	0 B	0 B
51.06	7.	0 B	0 B	0 B	0 B	0 B
51.07	8.	0 B	0 B	0 B	0 B	0 B
51.08	9.	0 B	0 B	0 B	0 B	0 B
51.09	10.	0 B	0 B	0 B	0 B	0 B
51.10	11.	0 B	0 B	0 B	0 B	0 B
51.11	12.	0 B	0 B	0 B	0 B	0 B
51.12	13.	0 B	0 B	0 B	0 B	0 B
51.13	14.	0 B	0 B	0 B	0 B	0 B
51.14	15.	0 B	0 B	0 B	0 B	0 B
51.15	16.	0 B	0 B	0 B	0 B	0 B
51.16	17.	0 B	0 B	0 B	0 B	0 B
51.17	18.	0 B	0 B	0 B	0 B	0 B
51.18	19.	0 B	0 B	0 B	0 B	0 B
51.19	20.	0 B	0 B	0 B	0 B	0 B
51.20	21.	0 B	0 B	0 B	0 B	0 B
51.21	22.	0 B	0 B	0 B	0 B	0 B
51.22	23.	0 B	0 B	0 B	0 B	0 B
51.23	24.	0 B	0 B	0 B	0 B	0 B
51.24	25.	0 B	0 B	0 B	0 B	0 B
51.25	26.	0 B	0 B	0 B	0 B	0 B
51.26	27.	0 B	0 B	0 B	0 B	0 B
51.27	28.	0 B	0 B	0 B	0 B	0 B
51.28	29.	0 B	0 B	0 B	0 B	0 B
51.29	30.	0 B	0 B	0 B	0 B	0 B
51.30	31.	0 B	0 B	0 B	0 B	0 B
51.31	32.	0 B	0 B	0 B	0 B	0 B
51.32	33.	0 B	0 B	0 B	0 B	0 B
51.33	34.	0 B	0 B	0 B	0 B	0 B

(*) POINTS AT NORMAL TIME INTERVAL

STATION NAME	TIME (HRS)	5400.	5500.	5600.	5700.	5800.	5900.
		6019.	6040.	6060.	6078.	6095.	6111.
		-97.	-99.	-99.	-98.	-96.	-93.
		-725.	-724.	-723.	-721.	-7017.	-110.
		-1.	-1.	-1.	-1.	-1.	-1.
		-9.	-9.	-9.	-9.	-59.	-1483.
		-724.	-723.	-722.	-721.	-1633.	-1631.
		-1.	-1.	-1.	-1.	-1.	-1.
		-1533.	-1533.	-1533.	-1533.	-1533.	-1533.
		-1.	-1.	-1.	-1.	-1.	-1.
		-1574.	-1574.	-1574.	-1574.	-1574.	-1574.
		-1.	-1.	-1.	-1.	-1.	-1.
		-1605.	-1605.	-1605.	-1605.	-1605.	-1605.
		-1.	-1.	-1.	-1.	-1.	-1.
		-1624.	-1624.	-1624.	-1624.	-1624.	-1624.
		-1.	-1.	-1.	-1.	-1.	-1.
		-1633.	-1633.	-1633.	-1633.	-1633.	-1633.
		-1.	-1.	-1.	-1.	-1.	-1.
		-1631.	-1631.	-1631.	-1631.	-1631.	-1631.
		-1.	-1.	-1.	-1.	-1.	-1.
		-1617.	-1617.	-1617.	-1617.	-1617.	-1617.
		-1.	-1.	-1.	-1.	-1.	-1.
		-1591.	-1591.	-1591.	-1591.	-1591.	-1591.
		-1.	-1.	-1.	-1.	-1.	-1.
		-1556.	-1556.	-1556.	-1556.	-1556.	-1556.
		-1.	-1.	-1.	-1.	-1.	-1.
		-1535.	-1535.	-1535.	-1535.	-1535.	-1535.
		-1.	-1.	-1.	-1.	-1.	-1.
		-1525.	-1525.	-1525.	-1525.	-1525.	-1525.
		-1.	-1.	-1.	-1.	-1.	-1.
		-1521.	-1521.	-1521.	-1521.	-1521.	-1521.
		-1.	-1.	-1.	-1.	-1.	-1.
		-1520.	-1520.	-1520.	-1520.	-1520.	-1520.
		-1.	-1.	-1.	-1.	-1.	-1.
		-1520.	-1520.	-1520.	-1520.	-1520.	-1520.
		-1.	-1.	-1.	-1.	-1.	-1.
		0.	0.	0.	0.	0.	0.

35	J.J.	36.
51	36	37.
51	36	37.
51	37	38.
51	39	40.
51	40	41.
51	41	42.
51	42	43.
51	43	44.
51	44	45.
51	45	46.
51	46	47.
51	47	48.
51	48	49.
51	49	50.
51	50	51.

100

32

PEAK OUTFLOW IS 5490.01 TIME 52.00 HOURS

PEAK

CFS	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
	5490.	5328.	3528.	1255.	180756.
CMS	155.	151.	100.	36.	5118.
INCHES		3.49	9.24	9.87	9.87
MM		86.65	234.61	250.60	250.64
AC-FT		2642.	6998.	7468.	7469.
THOUS CU M		3259.	8631.	9212.	9213.

HYDROGRAPH BOUTING

W/S OF PARK AVE - PARK RIDGE, N.J.

DEPTH CHANNEL ROUTING

CROSS SECTION COORDINATES--STA. ELEV. STA. ELEV.--ETC

	STORAGE	OUTFLOW								
0.00	1.18	2.49	3.90	5.45	7.12	9.44	14.77	23.41	35.35	54.03
50.60	67.97	86.46	106.14	126.93	148.87	171.95	196.17	221.53	248.03	264.73

33

AC-FT	THOUS CU IN	2480	3306	2680	3306	2480	3306	2680	3306
		-	-	-	-	-	-	-	-
		70	8685	70	8685	70	8685	70	8685

MAXIMUM STAGE IS 1118 6

MAXIMUM STORAGE =

STATION REACH1 REACH2 REACH3 REACH4

OUTFLOW	4.	4.	4.	4.
7.	5.	5.	5.	5.
3.	3.	2.	2.	2.
2.	2.	1.	1.	1.
1.	1.	1.	1.	1.
0.	0.	0.	0.	0.
0.	0.	0.	0.	0.
0.	0.	0.	0.	0.
1.	2.	5.	8.	13.
59.	72.	87.	108.	138.
672.	864.	1118.	1404.	1661.
3566.	3818.	4064.	4291.	4513.
5418.	5448.	5490.	5484.	5453.
4781.	4955.	4395.	4159.	3901.
2238.	22475.	21791.	1608.	1436.
764.	485.	485.	547.	488.
281.	281.	281.	547.	436.
241.	241.	241.	2225.	196.
				148.
				159.
				171.
				183.
				194.
				210.
				258.

	PEAK CFS	6-HOUR CFS	24-HOUR CMS	72-HOUR CMS	TOTAL VOLUME 180727. 5119
	5490.	5328.	3528.	1255.	
	155	151	100	14	

34

INCHES 3.49 .24 9.86 9.87
 MM 88.65 234.80 250.56 23.60
 AC-FT 2642. 6997. 7467. 7468.
 THOUS CU M 3259. 8631. 9210. 9212.

MAXIMUM STORAGE = 22.

MAXIMUM STAGE IS 117.6

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
FLows IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
AREA IN SQUARE MILES (SQUARE KILOMETERS)

RATIOS APPLIED TO FLOWS

OPERATION	STATION	AREA	PLAN	RATIO
HYDROGRAPH AT	LAKE	14.20 (36.78)	1 (155.48)	.50
ROUTED TO	DAME	14.20 (36.78)	1 (180.49)	.50
ROUTED TO	REACH1	14.20 (36.78)	1 (175.45)	.50

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
	STORAGE OUTFLOW	132.00 23.	132.00 23.	137.60 68.
	MAXIMUM DEPTH OVER DAM	0.	0.	4634.
PLAN 2	ELEVATION	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
	STORAGE OUTFLOW	132.00 23.	132.00 23.	137.60 68.
	MAXIMUM	MAXIMUM	MAXIMUM	TIME OF FAILURE
RATIO	OF RESERVOIR W.S. ELEV	DEPTH AC-FT	OUTFLOW CFS	HOURS

OF PMF	RESERVOIR W.S.ELEV	DEPTH OVER DAM	STORAGE AC-FT	OUTFLOW CFS	OVER TOP HOURS	MAX OUTFLOW HOURS	FAILURE HOURS
.50	137.87	.27	71.	5490.	8.00	52.00	0.00
RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS	RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
.50	6196.	118.0	51.50	.50	5490.	117.6	52.00

